

To the Voters of the Town of Bridgewater:

The following is a summary regarding the future of the school building. Recall, that a survey was sent out about the possibilities. The responses and options are listed below. The town has received reports from a realtor and an engineering firm. These reports are available for your inspection at the Town Office. 142 people responded to the survey.

Option 1. Rehab current building at taxpayer expense for continued use:

An engineering firm has inspected the building and tested for radon. The building has many deficiencies. There will be considerable expense to repair and renovate. Further expenditures will be required to meet state codes and standards. Some of these include repairs of the heating system, plumbing, and electrical. Roof repair or replacement as well as exterior maintenance and a drainage system will also be necessary. The town would need to invest a considerable amount of time and money on this property over the next several years. (2) Survey respondents favored this option.

Option 2. Convert site into multi-purpose structure:

The town has also gotten a quote for demolition and excavating to bring the ground level with the abutting property. The cost would be slightly under \$100,000. The town would then concentrate on building a new handicap accessible building to accommodate meetings, shelter and future emergency services. A new building will require a bond. The amount, obviously, will be determined by the size and complexity of the building. Any bond will have to be approved by a vote. (84) Survey respondents favored this idea.

Option 3. Sell the building:

An independent realtor has inspected the building and made findings that comparable sales within the area may bring a sales price for the building of approx. \$300,000. The building most likely would be on the market for some time. This option will require ongoing maintenance expense and various soft costs such as insurance, etcetera. (48) Survey respondents favored this alternative.

Option 4. Other alternatives:

Variations on options 1 & 2 above. (8) Survey respondents made these suggestions.

Other factors: The Southgate House and The Brick Schoolhouse water requirements are supplied by the school building. Whatever the outcome; this will need to be addressed. Remember that the town will need a handicap accessible facility that can hold a Town Meeting. The future requirements of an emergency services/ shelter building should be part of any decision process.

We realize that the above information is only a small indicator of the data that has been collected but we wanted to update you as to the status of this project. We are in hopes of bringing this to the voters either this fall or at the next town meeting. Once again, reports can be inspected at the town office.

Selectboard Members,

Norman Martin II, Chair
Mary Oldenburg
John Timken

CRITERIUM[®] LALANCETTE ENGINEERS

PO BOX 6348
RUTLAND, VT 05702-6348
TEL 802-747-4535
800-639-4535
FAX 802-775-2307
info@criterion-lalancette.com

BUILDING INSPECTION REPORT



of
Bridgewater Village School
7313 US Route 4
Bridgewater, VT 05034

for
Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
Job #:16-36926

by
Richard Lalancette, P.E.
Board Certified Building Inspection Engineer

Report Date:
May 27, 2016

**LICENSED
PROFESSIONAL
ENGINEERS**

BUILDING INSPECTIONS
ANALYSIS & DIAGNOSTICS
RESERVE STUDIES
CAPITAL NEEDS ASSESSMENTS
ENVIRONMENTAL TESTING

Visit our website:
<http://criterion-lalancette.com>




Table of Contents

SUMMARY	1
INTRODUCTION	2
DESCRIPTION	4
SITE	4
STRUCTURE	5
BASEMENT WATER.....	8
VENTILATION.....	9
HEATING.....	9
ENERGY EFFICIENCY	10
PLUMBING.....	11
ELECTRICAL	13
INTERIOR.....	14
EXTERIOR	16
ROOFING.....	17
CHIMNEY, HAZARDOUS MATERIALS AND SAFETY	18
GENERAL.....	20
CONCLUSION.....	21
MAINTENANCE PLAN	
PHOTO LOG	
INSPECTION CHECK LISTS	
AGREEMENT FOR SERVICES	
PROFESSIONAL QUALIFICATIONS AND EXPERIENCE	
PRE-TITLE CHECK LIST	
GLOSSARY	

CRITERIUM[®] LALANCETTE ENGINEERS

PO BOX 6348
RUTLAND, VT 05702-6348
TEL 802-747-4535
800-639-4535
FAX 802-775-2307
info@criterium-lalancette.com

May 27, 2016

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
7335 US Route 4
Bridgewater, VT 05034

Re: Bridgewater Village School
7313 US Route 4
Bridgewater, VT 05034
Job #16-36926

Dear Town Select Board & Ms. Robinson:

At your request, a structural and mechanical inspection of the above property was performed on May 25, 2016. This inspection was performed by and report written by Richard Lalancette. For your interest, a copy of Mr. Lalancette's resume is attached.

The report that follows has been prepared from the perspective of what an owner of this property would benefit from knowing. Thus, it discusses many things beyond those, which are of immediate concern. Therefore, the report needs to be read in its entirety to understand fully all the information that has been obtained.

For your convenience, we have prepared the following summary to highlight the condition of the major systems of the property. Please refer to the appropriate section of this report for a more detailed discussion of these systems.

Summary

The structural system is in need of repair.

The heating system is operational.

The plumbing system is in need of minor repair.

The electrical system is in need of minor repair and upgrading.

The exterior is in need of regular maintenance and repair.

The roof is in need of repair/replacement.


In summary, we consider this property to be in below average condition when compared to others of similar age and construction type. This is primarily because of the amount of deferred maintenance noted. As a result, this property needs considerably more renovation, rehabilitation, and maintenance than most we examine. You may expect to invest a considerable amount of time and money in this property over the next several years.

In addition to these general condition statements, this report covers repairs and maintenance. (See attached Maintenance Plan.)

**LICENSED
PROFESSIONAL
ENGINEERS**

BUILDING INSPECTIONS
ANALYSIS & DIAGNOSTICS
RESERVE STUDIES
CAPITAL NEEDS ASSESSMENTS
ENVIRONMENTAL TESTING

Visit our website:
<http://criterium-lalancette.com>



Introduction

The conditions, recommendations, and suggestions contained herein are the result of a visual inspection as of this date and are presented to make this property a better and more comfortable place to live. We do, of course, look for problems, particularly those we would consider major deficiencies in the property. We generally define a significant deficiency as one that would cost approximately \$500.00 or more to correct. Any property will have minor items deserving attention. Often these are matters of personal preference that are mostly noticed by the property owner. Therefore, it is not our intent to detail every minor defect we might find.

Our inspection and report have been conducted in compliance with the Standards of Practice and Code of Ethics of the American Society of Home Inspectors (ASHI) www.ashi.org, and in a manner consistent with that level of care and skill that is ordinarily exercised by members of the profession practicing under similar conditions at the time the services are performed.

This inspection report is limited to observations made from visual evidence. No destructive or invasive testing was performed. The report is not to be considered a guarantee of condition and no warranty is implied.

For your reference while reading the report that follows, the following definitions may be helpful:

- Good - Component or system is sound and performing its function. Although it may show signs of normal wear and tear, some minor rehabilitation work may be required.
- Fair - Component or system falls into one or more of the following categories: a) Evidence of previous repairs not in compliance with commonly accepted practice, b) Workmanship not in compliance with commonly accepted standards, c) Component or system is obsolete, d) Component or system approaching end of expected performance. Repair or replacement is required to prevent further deterioration or to prolong expected life.
- Poor - Component or system has either failed or cannot be relied upon to continue performing its original function as a result of having exceeded its expected performance, excessive deferred maintenance, or state of disrepair. Present conditions could contribute or cause the deterioration of other adjoining elements or systems. Repair or replacement is required.

All ratings are determined by comparison to other buildings of similar age and construction type. Further, some details of workmanship and materials will be examined more closely in higher quality properties where such details of workmanship and materials typically become more relevant.

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Bridgewater Village School
Page 3

Attached are the actual inspection check lists which contain additional information. These should be considered part of the overall evaluation and report.

This report is based on an examination of the major systems in this property; specifically the heating, plumbing, electrical, and structural systems. This report is an opinion about the condition of this portion of the building. It is based on visual evidence available during a diligent inspection of all reasonably accessible areas. No surface materials were removed, no destructive testing undertaken, nor furnishings moved. This report is not an exhaustive technical evaluation. Such an evaluation would cost many times more.

Our inspection and report do not include code compliance, mold investigations, environmental investigations, indoor air quality analysis, municipal regulatory compliance, subsurface investigation, verification of prior uses, or records research related to the property.

Owning any property involves some risk. Even the most comprehensive inspection cannot be expected to reveal every condition you may consider relevant to your ownership. Further, without disassembling the building, not everything can be known.

As Professional Engineers, it is our responsibility to evaluate available evidence relevant to major systems in this property. We are not, however, responsible for conditions that could not be seen or were not within the scope of our service at the time of the inspection.

Our report is not intended to determine the insurability of your property or any of its components, materials or systems. Insurance companies use many different standards and criteria to determine what is or is not covered under a property owner's policy. For example, some do not cover certain types of roofing while others avoid certain types of siding.

Our inspection does not make any attempt to know or verify the prior uses of this property and cannot determine whether or not illegal activities have been engaged in on or near the property, including but not limited to, the use or manufacture of illegal substances, criminal events or the presence of substances banned or controlled by federal, state or local law.

We performed a standard inspection per our agreement for services. A copy of this agreement is attached for your reference.

We will be discussing many different subjects in this report as well as offering recommendations for changes and improvements to this property. As you read the report, pay particular attention to our notes regarding the fact that many of our observations and recommendations are typical of many properties we look at. Thus, while it may seem that there is some work to do during the next five to ten years, keep in mind that no property is perfect and all deserve some care, attention and upgrading.

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Bridgewater Village School
Page 4

For purposes of this report, all directions (left, right, rear, etc.) are taken from the viewpoint of an observer standing in front of the building and facing it.

Photographs are provided as a courtesy for your reference only. Please note that photographs of all defects and deficiencies cannot be and are not provided.

Description

This property is located on the north side of Route 4 in Bridgewater, Vermont. The front of the building faces south.

The building is a 2½ story, large-sized building formerly used as a school.

The exterior siding consists of wood clapboards.

The roof covering is a combination standing seam metal, membrane, and asphalt shingles.

There is a basement under all of this building, most of which has been finished off.

Site

The site is located on the north side of Route 4 in Bridgewater, Vermont, west of the Bridgewater Town Offices.

The property is identified by signage near Route 4 and a building-mounted sign on the front of the building.

There is one access driveway to the property from Route 4. The access driveway is paved with asphalt and continues along the east side of the building.

Along the east side of the building, the asphalt is in fair to poor condition. There is evidence of cracking and settlement and repairs should be anticipated.

There is a paved recreation area at the rear of the building. This paving is in fair to poor condition with cracking and settlement noted. Repair or replacement is needed.

The site of the building itself is fairly flat.

The site is elevated along the west side of the building. This area generally drains to the east.

At the north side of the building there is a hillside which generally drains to the south.

The east side of the building generally drains to the east.

The site drainage is fair to poor. Low spots were noted adjacent to the building. Regrading is needed to promote positive drainage.

There is what appears to be a perimeter drain at the north or rear of the building. The outlet for this drain could not be determined at the time of inspection.

There is pedestrian paving at the front of the building and at the west side of the building. This pedestrian paving is in fair to poor condition with cracking and deterioration noted.

There is a play area at the west side of the building which is enclosed by a six foot high chain link fence. This fencing is in fair condition. Portions are damaged and leaning. Repair is needed at this time.

The short timber retainers at the play area are leaning and repair or replacement is needed.

Site lighting is provided by a building-mounted light at the front entry to the building. At the right side of the building, there are two building-mounted spot lights to illuminate this area. At the left rear entry to the building, there is a single canopy light.

The site lighting appears to be marginal for the needs of this property.

Structure

Our evaluation of this structure is based on many indirect observations. Because we cannot see a significant portion of the framing, we look for cracks, bulges, and other evidence of distress or deterioration to help us evaluate the structural condition. As with any limited inspection, it is possible that there are structural deficiencies that cannot be seen.

The following areas are inaccessible and limited the extent of our structural inspection:

- Roof framing above insulated sloped ceilings at the rear of the building.
- Center attic area remote from the access opening.

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Bridgewater Village School
Page 6

- Roof framing above the finished attic ceilings.
- First floor framing above finished lower level ceilings.
- Foundation walls where finished off and insulated.

Access to the upper front attic area is provided by a stairway in the upper level front hall. Conditions in this attic area were observed by entering the space.

Access to the center attic area is provided by an access opening in the upper front attic area. Conditions in this attic area were observed from the access opening.

Limited visual access to the roof framing at the rear of the building is provided through the dropped ceiling at the rear second floor of the building. Conditions in this attic area were observed through the dropped ceiling.

The basic construction of the front of this building consists of concrete foundation walls and a column-girder system for support of the first floor level joist members. This is a standard method of construction.

The basic construction of the rear of this building consists of concrete and block foundation walls and a floor joist system that spans the distance from foundation wall to foundation wall. This is also a standard method of construction.

Where visible, the foundation walls are generally in good to fair condition.

Some cracking of the concrete foundation walls was noted in the front basement area. The full extent of this cracking could not be determined due to the finishes in this area.

The cracks in the foundation walls, both inside and outside, should be properly repaired. Sealing these cracks will help to prevent moisture penetration/leakage and will help to prevent them from getting larger.

One of the better ways to seal these cracks is from the outside. First, chip a v-groove in the concrete along the length of the crack (all the way to the footing, if necessary). The root of this v-groove should then be filled with a high-quality caulking (epoxy, latex, or polyurethane), mortar applied to fill the groove, and, finally bituminous basement waterproofing applied.

Within the unfinished basement, there has been some cracking of the concrete slab. This is common and to be expected. There is no apparent structural deficiency related to this condition.

Evidence of rot and deterioration was noted in the trim at the front basement windows. This rot and deterioration may extend into the structural framing in this area. The full extent of this condition could not be determined at the time of inspection. These areas should be opened for further investigation and the proper repairs be made.

In the front lower level area where the sheetrock has been removed, significant rot and deterioration was noted in the bottom plate of the interior finish walls. This indicates long term seepage into this area. Replacement of these sill plates should be planned for. The use of pressure treated materials is recommended to minimize future deterioration.

While there is no visible evidence of any significant dry rot present elsewhere in this structure, it should not be assumed that no dry rot exists in any of the inaccessible areas. Dry rot can result from moisture accumulating underneath the siding, behind trim, or within the wall cavities should the normal drying process be restricted by insulation or other obstacles. Therefore, it is possible that you will encounter some dry rot if you undertake any projects that involve disassembly of the portions of this structure normally inaccessible to visual inspection. This is typical for any building.

It has also been our experience that rot can often be found in those portions of the sill that are not commonly visible (i.e. behind the siding, the bottom surface adjacent to the foundation wall, etc.). Thus, you may discover some deterioration in the sill and related framing when any repair work is undertaken that exposes these normally inaccessible portions of the structure.

There was no evidence of any significant destructive insect activity at the time of our inspection. In general, this is not a serious problem in this area. However, if you see any significant number of insects around at any time, you should consult a specialist who can identify them.

Conditions exist in this building that would encourage carpenter ant and other insect activity. Specifically, these insects prefer to nest in damp environments. Therefore, all areas where wood is close to the ground and likely to become moist at various times of the year should be kept under observation for possible insect activity. Also, it is possible that you will encounter some carpenter ant activity and/or damage if you undertake any projects that involve disassembly of the normally inaccessible portions of this structure.

In the front attic area, trusses have been installed to provide for a clear span at the upper level classroom ceilings. The truss system in the left attic has been braced to minimize movement. The truss system in the right attic area has experienced significant warping and movement. Bracing of this truss system is needed.

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Bridgewater Village School
Page 8

There has been some normal settlement of these premises, which is to be expected. This is indicated by some sagging floors, separations between floor and base moldings, etc. However, there are no indications of structural instability.

In general, jacking up of floors to make them level is not recommended. This often causes more problems than it solves.

Overall, we consider the structural condition of this building to be average.

Basement Water

Evidence of moisture and seepage through the foundation walls was noted. This is the result of the type and condition of the foundation walls, ground sloping conditions, soil conditions, etc. Specifically this evidence includes:

- Water stains on the walls.
- Water stains on wood in contact with the floor.
- Water stains on the floor.
- Water stains at the joint between the floor and wall.

If significant amounts of water should enter the basement area, it would be important to establish some type of drainage system, either through drain pipes or a sump pump, to remove such water quickly.

The only sure way to correct this condition may be to excavate the exterior foundation walls and apply a membrane waterproofing. In addition, drain tiles, connected to a suitable outlet (preferably daylight) should be installed along the exterior base of the foundation walls to carry water away from these walls.

All exterior drains need to be kept clean, clear, and functioning at all times.

Regrading of low areas and ground sloping toward the building is recommended. In general, water should flow positively away from the building.

Ventilation

Ventilation of insulated attics is important. The amount of ventilation should be one square foot of vent area for each 300 square feet of attic floor area.

There are no fresh air louvers in the front attic of the building. If windows in this area are left open, rain may enter. It is therefore suggested that screened louvers on each end of the building or a continuous ridge vent be installed, for proper ventilation and prevention of moisture condensation.

For this area, additional ventilation through the soffit is recommended. The insulation should be pulled back to allow air to flow freely through the soffit and into the attic space. Without that, significant problems with ice buildup along the edge of the roof and condensation within the attic space itself could occur. The soffit is the underside of the roof overhang.

From a ground inspection it was noted that soffit and gable vents have been provided for the attic area at the rear of the building.

Basement ventilation is extremely important to minimize condensation and the effects of any water that might seep into this area. We recommend keeping all basement windows open throughout the warmer months of the year. As appropriate, they should be equipped with screens to prevent rodent and insect entry.

If natural ventilation is inadequate, installation of one or more dehumidifier units in the basement area is recommended for humidity control.

Indoor air quality is a growing concern. There is evidence of some moisture accumulation in the basement of this building. You may want to consider additional tests of the air quality to determine whether there are any significant levels of mold, mildew or other airborne materials that might be troublesome.

Heating

Heat for this building is provided by two oil-fired, forced hot water heating units connected in series. These units consist of a burner (the small device located at the front), a boiler (in which the water is heated), and five circulating pumps (to distribute the water throughout the building).

At this time, heat distribution appears to be controlled through nine zones, each with its own thermostat.

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Bridgewater Village School
Page 10

Zone control of this forced hot water system depends on electrically operated zone valves. These valves are a common source of maintenance problems and should be checked regularly for proper operation.

The heating units appear to be in good to fair condition. However, the heating units are nearing the end of their serviceable life and more than normal repairs or replacement should be planned for.

We recommend that the heating unit be cleaned and serviced at least once each year. This servicing should include all gauges, controls, the firebox, etc.

Further, the proper cleaning of the chimney flue serving the heating unit is recommended every three to five years.

Various baseboard heating unit enclosure repairs throughout the building are needed.

Several of the older radiators are disconnected and no longer in service. This should be further investigated and the proper repairs be made.

There is an air handling unit located in the attic space which is also equipped with a heating coil. At the time of inspection, this system did not appear to be serviceable. This should be further investigated and repaired as necessary.

We recommend that this unit be cleaned and serviced at least once each year. This cleaning and servicing should include the motor, blower, filter, etc.

For maximum efficiency with this air handler, it will be necessary to clean or replace the air filters regularly. These should be cleaned or replaced at least once a month, or more frequently if inspections indicate that they are becoming clogged with dust and dirt. Clogged filters can dramatically reduce the efficiency of your heating system.

Energy Efficiency

In any building, the two most important contributors to energy efficiency are the conduction and infiltration losses. Conduction (or direct loss through the walls and ceiling) is primarily controlled by insulation. Infiltration loss (drafts or air leakage) is controlled by caulking and weatherstripping.

In this property, there is an opportunity to improve both the conduction and infiltration losses.

There appears to be 4 to 10 inches of insulation installed in the accessible attic areas of this building. Six inches is considered to be a minimum amount with twelve inches as an ideal.

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Bridgewater Village School
Page 11

There is evidence that some of the walls of this building are insulated.

At this time, it is uncertain whether or not there is insulation in all of the walls of this building.

Not all of the windows are equipped with storm windows. Installation of these will cut down drafts and loss of heat, which will result in fuel savings, besides adding materially to the comfort of the building. These are recommended.

Some of the windows in this building are thermal-pane (double-glazed) windows. They are in good to fair condition. In general, these do not require additional storm windows.

This building is equipped with aluminum-framed storm windows on some of the windows. These were in good to fair condition at the time of the inspection.

All of the storm windows should be checked to be sure that the drainage holes toward the bottom are kept open to permit proper drainage of any moisture that accumulates between the two windows.

For maximum energy efficiency, the storm windows must work together with the primary windows. Both must be tight to assure a static air mass between the two. Therefore, a good quality weatherstripping should be applied to all of the older primary windows throughout the building.

Several of the exterior doors are equipped with weatherstripping which is, in general, in poor condition. We recommend upgrading the weatherstripping for maximum energy efficiency. The threshold sweep at the bottom of each exterior door should not be overlooked.

To be certain that you are not wasting energy on the production of hot water, you should check the temperature of the hot water produced. If it is above 130 degrees, we recommend that you reduce it to that level to minimize your hot water energy requirements. To be most accurate, use a thermometer at the hot water faucet.

Plumbing

This building is apparently served by its own well. This well is shared with the Town Offices and an adjacent building.

We recommend obtaining a water quality test to determine the quality of water being produced by this well.

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Bridgewater Village School
Page 12

The submersible pump could not be fully inspected. The visible equipment (tank, controls, etc.) is in good condition.

The water system is equipped with two sediment filters and two ultra-violet filters. These were unpowered, bypassed, and not in operation at the time of inspection. Thus, we are unable to comment on their operation and serviceability.

Where visible, the plumbing distribution piping in this building is primarily copper. This system was in operating condition at the time of the inspection.

The faucet at the janitor's sink is loose and needs to be properly secured.

Replacement of the older fixtures at the upper level front powder room should be planned for.

The drain lines in this building consist of PVC and cast iron piping. Where visible, this system is in good condition.

As we understand it, this building is served by municipal sewer, which was operational at the time of the inspection. Little problem need be anticipated in that area.

There is a pump in lower level storage closet that is used to pump waste from the janitor's sink to the main waste pipe. At the time of the inspection, this pump was operational.

There is a pump in kitchen that is used to pump waste from the kitchen sink to the main waste pipe. At the time of the inspection, this pump was operational.

Domestic hot water is provided as an integral part of the heating system. Its serviceability depends, of course, on the proper operation of the heating unit itself.

Domestic hot water is heated in the hot water storage tank by an internal coil. The water passing through this coil is heated in the boiler and a separate circulating pump forces it through the heating coil. The temperature of the water in the storage tank is maintained by starting and stopping the circulator in conjunction with the boiler.

The water storage tank appears to be in fair condition, and its size should be adequate for the normal needs of this size building.

Although in operation, the water heater is old and its replacement in the not-too-distant future should be anticipated.

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Bridgewater Village School
Page 13

The evidence of leakage noted around the pressure relief valve on this water heater. This should be further investigated and corrected as necessary.

Electrical

Our investigation of the electrical system is limited to the visible components, the entrance cable, meter box, service panel, outlets and switches, and the visible portions of the wiring. A larger portion of the electrical system is hidden behind walls and ceilings, and obviously, all the conditions relating to these unseen areas cannot be known. Where possible, the cover of the service panel is removed to investigate the conditions in it.

While some deficiencies in the electrical system are readily discernable, not all conditions that can lead to interruption of electrical service, or that are hazardous can be identified.

A typical electrical system consists of two distinct components - the electric service entrance and the electric circuits. The service entrance determines the capacity of the electric power available to the property. The electric circuits distribute power through the building.

Electrical devices in a property typically use either 120 or 240 volts. The major appliances such as clothes dryers, kitchen ranges, water heaters, and electric heating units require 240 volts. General purpose circuits (lighting, outlets, etc.) require 120 volts.

The service entry conductors consist of aluminum.

The main service panel is located in the left front electrical closet.

The main service switch is located in the main service panel.

Auxiliary service panels are located in the left front electrical closet and in the right rear second floor office area.

The electrical system, consisting of a three-wire 120/240 volt service with 200 amperes available, is adequate to serve the needs of this property as it now stands.

It would be wise to have each of the present circuits fully identified so you will know what electrical load is on each circuit. If you have any doubts, it is suggested that a competent electrician be consulted.

The general condition of the wiring and fixtures is good to fair. A spot check of electrical outlets and switches revealed no major problems.

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Bridgewater Village School
Page 14

Knob and tube wiring was noted in the front upper attic area. For the most part, it appears that this wiring has been abandoned. However, we could not confirm that all knob and tube wiring in this building has been abandoned.

The outlet in the electrical closet appeared to be unpowered at the time of inspection. This should be further investigated and corrected.

The ground fault interrupt outlet in the women's room did not trip properly when tested. This should be further investigated.

Some of the receptacles have been painted. Replacement of these receptacles is recommended.

All uncovered outlets should be equipped with proper cover plates.

The missing lighting covers noted in the lower level multi-purpose area need to be replaced.

The missing lens for the light at the right stairway needs to be replaced.

This building is equipped with ground fault interrupt (GFI) circuits in the lower level men's and women's rooms and near the sink in the right lower level classroom. . The purpose of a GFI circuit is to provide positive protection against a shock hazard since it will "trip" almost instantaneously, thus protecting you. The GFI circuit breaker operates the same as other circuit breakers -- should it "trip," simply reset it for continuing operation. Periodically, you should test the GFI circuit breaker for proper operation. There is a test button either at the outlet itself or in the electrical service panel. When you push the test button, the GFI circuit breaker should trip to the off position.

We recommend the installation of additional ground fault interrupt (GFI) circuit breakers for the upper level rear powder room and the kitchen outlets.

This building is equipped with provisions for the use of a portable electric generator. This equipment could not be tested as part of our inspection.

Overall, the electrical system is in good to fair condition.

Interior

As a responsible property owner, you are best able to judge the condition of the interior finish of the rooms. In this section of the report we are concerned with those things which are technically and financially significant. For example, stains which might indicate roof or plumbing leaks, older wall or

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Bridgewater Village School
Page 15

ceiling materials which may require repair/replacement; the use of substandard materials on interior walls or ceilings; or the quality and condition of such items as the doors, windows, and cabinetry are those things which can affect the overall quality and condition of a building.

Overall, the quality of the materials used throughout this building is average. The doors, windows, cabinetry, hardware, molding, etc. are serviceable.

Generally, the interior walls and ceilings of this building are finished with ceiling tile, plaster, sheetrock, tin, Formica, fiberboard, and wood.

Refinishing of many of the lower level walls is needed.

Extensive ceiling tile repairs or replacement throughout the property are needed.

Some repair to the tin ceiling in the upper level hall is needed.

All evidence of leaks should be investigated and corrected as necessary. These were noted on various walls and ceilings throughout the building.

Squeaking floors are typically the result of loose floorboards which can be minimized by renailling or shimming.

As is typical with a building of this age, various floor and floor board repairs and reinforcement are indicated.

The doors in this building are of a standard quality and are in serviceable condition. While serviceable, the doors need some adjustment and minor repairs. This is typical with a building of this age.

A few of the doors are in poor condition and replacement should be considered.

While serviceable, the cabinetry in this building is somewhat below standard. More than average maintenance and repairs should be anticipated.

The wood trim and other woodworking in this building is of standard quality and workmanship.

All exhaust fans and exhaust ductwork should be cleaned and serviced.

Unless otherwise noted on the inspection checksheets, none of the appliances and/or equipment on these premises were tested.

Exterior

The exterior walls of this building are covered primarily with wood clapboards. At this time, they are in good to fair condition.

A few repairs are indicated, including:

- Deteriorated siding at the right rear entry.
- Damaged siding at the rear of the building.

Some exterior wood trim repairs and/or replacement are indicated. Specifically, the following was noted:

- Rot in the trim members at the left front lower level windows.
- Rot in the trim members at the right front lower level windows.
- Rot in the sashes at the right front lower level windows.
- Cracked lower trim at the right bulkhead entry.
- Damaged trim at the right side of the building near the propane tank.
- Damaged trim at the right rear entry.
- Cracked lower trim at the right rear of the building.
- Rot and deterioration in the soffit fascia trim at the rear of the building.
- Rot and deterioration in the lower drip edge along the rear of the building.
- Rot in the trim members at the left rear lower level window.
- Rot in portions of the corner trim at the rear of the building.

The entry at the left rear door has heaved and settled. This entry has pulled away from the main building. There is a gap in the siding members where the entry joins the building. Repairs should be planned for.

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Bridgewater Village School
Page 17

Several large gaps around the building have been sealed with spray foam insulation. This spray foam has been poorly trimmed and finished. Improvement is needed.

Repainting the exterior sidewalls and trim should be accomplished as soon as possible. Any new painting should be done only after all exposed wood has had an opportunity to dry, all loose paint is scraped away, and a proper primer is applied.

At the time of repainting, we recommend that caulking compound be placed around all window and door frames, where they make contact with the sidewalls of the building as well as in the joints of different building materials. This caulking prevents drafts and possible moisture penetration. This is not expensive and is important.

Many of the windows in the building are old and, while in operable condition, maintenance and repairs will be an ongoing demand. You should upgrade or rehabilitate the windows in the near future.

Some window repairs and adjustment are needed. This includes replacement of any broken sash cords.

Putty work around several individual panes is indicated.

Many of the older windows in this building are cracked and should be repaired.

The remaining windows in this building are of standard quality. While some maintenance and repairs will always be needed, these should be serviceable for many years to come.

Some repair to the plastic trim around several of these windows is needed.

Seals in thermal pane windows can break down within ten to fifteen years of their installation. Condensation developing between the panes of such a glass unit is indicative of a broken seal. These conditions are not always visible, however, depending on temperature and humidity conditions. Usually, repair of broken seals requires replacement of the damaged glass unit.

All missing and damaged window screens should be replaced.

Roofing

The roof was observed from a ladder placed at the eaves.

The roof covering at the front of the building is of standing seam metal. This roofing is in good to fair condition.

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Bridgewater Village School
Page 18

Some repair to the standing seam metal roof at the front valleys is needed.

The roof covering on the rear of the building is of membrane. This roof surface is in fair to poor condition. Many of the seams are beginning to open up and several of the patches have come loose. The roof appears to be 24 years old. Resurfacing in the near future should be planned for.

The asphalt shingle roof coverings on the left front and right front bulkhead entries are in poor condition and resurfacing is needed at this time.

The roof covering at the right rear entry is of asphalt shingles. It is in fair condition.

With any roof, regardless of age, minor leakage should be expected from time to time. This can occur along the edges of the roof, at joints between different roof surfaces and around the chimney. Normally, these repairs are easily accomplished.

There were no gutters on this building.

Chimney, Hazardous Materials and Safety

While some references to hazardous materials and code compliance may be made, our report is not to be considered a complete investigation for code compliance, toxic wastes in the adjacent soils, hazardous materials, or public records affecting this property. Such an investigation would be more costly and beyond the scope of our normal inspection.

While we often comment on major code violations, as we mentioned, this report should not be construed as a specific code compliance investigation. Further, since this is a commercial building, it is subject to many local and state ordinances and codes which do change from time to time.

Where visible, the chimney appears to be in good to fair condition at this time. It appears to be structurally stable.

Whether or not this chimney is lined could not be determined at the time of inspection.

We recommend that it be cleaned and carefully inspected internally in order to fully assess its current condition.

This building is apparently equipped with an underground oil tank. We recommend that this tank be checked to ensure it is not leaking.

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Bridgewater Village School
Page 19

Removal of this tank and replacement with an above-ground storage tank is recommended.

A bottled gas tank is located outside this building. If kept well maintained, this tank is normally quite safe. However, it is important to be sure that all of the fittings are checked regularly, even if you are not using the gas and the tank is not being filled regularly. A leak in such a tank can cause a serious fire hazard and possible explosion.

There is a fire alarm system in this building. Exactly how well this system is functioning and what areas it serves are not known at this time.

The alarm system was inspected in July of 2015. No violations were noted at that time.

This building is also equipped with a wet pipe sprinkler system. This system was inspected in August of 2015. No violations were noted at that time.

While no suspected asbestos-containing material (ACM) was observed, some ACM may be present in this building which was not visible during our inspection. In general, if these materials are not releasing fibers into the air, they are not considered to be a health hazard. If future renovation work uncovers ACMs, however, they would need to be handled in accordance with applicable state and Federal regulations.

Radon is the number one cause of lung cancer among non-smokers and, according to EPA estimates, is responsible for approximately 21,000 lung cancer deaths every year. Radon is a naturally occurring radioactive gas released in rock, soil, and water and can build up to dangerous levels inside any building. This means new and old buildings, well-sealed and drafty buildings, and buildings with or without a basement. Radon gas is odorless and invisible and the only way to know if the building has a radon problem is to test for it. If discovered, radon is relatively easy to control through effective ventilation.

At your request, a radon test was conducted in this building. The results of this test will be forwarded to you separately.

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Bridgewater Village School
Page 20

Since this building was apparently constructed and painted before 1977, it is quite likely that any older paint that remains (and it is virtually impossible to remove all paint from any building) may contain lead. Even lab analysis of a sampling of the paint in this building could not guarantee that no lead based paint exists anywhere. Thus, caution should be exercised when working around any of the painted surfaces, particularly during any remodeling work. Also, you should prevent children or pets from chewing on the woodwork.

The copper plumbing in this building may be joined with a lead-based solder. In 1986, Federal law prohibited the use of lead solder on pipes that carry drinking water. In addition, many plumbing fixtures, such as chrome-plated faucets, are made of brass, which contains lead. When water stands for several hours or more in plumbing systems containing lead, some lead may dissolve into the drinking water. To satisfy you that unhealthy levels of lead are not present, the water could be tested.

General

The following are a few additional comments that may be of interest to you regarding this property.

In connection with the concrete slab portion of this property, condensation on the floors sometimes occurs, particularly in the summer. This is quite common and to be expected.

Further, it must be remembered that without heat in the floor, concrete slabs may be cold.

Some cracking and settlement was noted in the entry platform at the front of the building. Future repairs should be planned for.

The trees and shrubs around this building are too close and may cause premature deterioration of the paint and siding. These should be trimmed to provide several inches clearance from the sidewalls and several feet above the roof.

Proper regrading to eliminate low areas around the building and ground sloping toward the building is needed.

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Bridgewater Village School
Page 21

Although there is no evidence of problems with the capacity of the well serving this property, private wells such as this can be unpredictable. Seasonal variations are common. Also, fluctuations are likely if other buildings are built in the area.

There has been some settlement of the bank at the left rear of the building. Some erosion control in this area is recommended.

The installation of a cap on the cleanout for the perimeter drain system at the rear of the building is needed.

Conclusion

In general, keep in mind that many of the suggestions we have made in this report represent improvements to this property rather than deficiencies. Thus, much of the work we suggested can be handled as time, finances and personal preference dictate. Owning any property can be overwhelming. Thus, keep in mind that not all of the things we have recommended must be done immediately.

Additional data concerning this property are noted on the enclosed individual inspection sheets.

This report has been prepared in strict confidence with you as our client. No reproduction or re-use is permitted without express written consent. Further, we will not release this report to anyone without your permission.

This report is not to be used as a basis for determining the value of such premises. This report is not to be construed as a guaranty, or warranty of the premises or equipment therein or of their fitness for use. Since this was, as noted previously, a visual inspection of these premises, it is suggested that consideration be given to engaging the services of a competent contractor to determine the extent of the various defects/deficiencies noted herein and to provide cost estimates.

There is no one way to build, renovate or remodel a property. As a result, you may encounter contractors whose opinions about the condition of this property will differ from ours. We cannot be responsible for any action you may take based on those opinions unless we have the opportunity to review the situation and examine the relevant conditions before any repairs and/or modifications are made.

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Bridgewater Village School
Page 22

Many things have been discussed in this report. However, we realize that there may still be other things of interest to you that have not been discussed. Therefore, we encourage you to call with any additional questions you may have.

Thank you for the opportunity to be of assistance to you.

Sincerely,



Richard Lalancette
Board Certified Building Inspection Engineer
State of Vermont Property Inspector #143.0116420

RL/sjo
Enclosures

Maintenance Plan

In addition to these general condition statements, this report covers repairs and maintenance. To help provide a perspective for the work that we have recommended for this property, the following schematic maintenance plan is offered. This list should not be considered all-inclusive. Surely, there will be other things you will want to do that can be made a part of this list during the next several years. Our purpose is to help you organize some of the work that we have recommended with emphasis on those things that need attention within the next year or so.

Within the next year of ownership:

- Heating unit maintenance
- Heating system repair
- Repair air handling unit in attic
- General electrical system repair
- Additional GFI installation
- Plumbing fixture repairs
- Well water testing
- Possible water heater replacement
- Exterior trim and siding repair
- Exterior sidewall painting
- Exterior caulking
- Window upgrade/rehabilitation
- Storm window installation
- Partial roof resurfacing
- Roofing repairs
- Chimney cleaning
- General structural repairs (see report)

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Maintenance Plan
Page 2

- Foundation crack repair
- Improve basement drainage
- Regrading
- Improve attic/soffit ventilation
- Additional insulation
- Test GFIs monthly

Within the next five years of ownership:

- Continued annual heating unit maintenance
- Possible heating unit replacement
- Continued window upgrade/rehabilitation
- Pedestrian paving repairs
- Fencing repairs
- Chimney cleaning
- Test smoke alarms monthly
- Test GFIs monthly
- Continued general maintenance

Within the next ten years of ownership:



- Continued annual heating unit maintenance
- Exterior sidewall painting
- Chimney cleaning



Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Maintenance Plan
Page 3

- Test smoke alarms monthly
- Test GFIs monthly
- Continued general maintenance

Photo Log

<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1852</p> <p><u>Description:</u> Front of building</p>		<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1851</p> <p><u>Description:</u> Access driveway to property</p>	
---	--	---	---

<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1854</p> <p><u>Description:</u> Front of building and walkway</p>		<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1853</p> <p><u>Description:</u> Signage near road</p>	
---	---	---	--




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1855

Description:
Deterioration in front
walkway




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1856

Description:
Deterioration in front
walkway




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1857

Description:
Deterioration in front
walkway




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1858

Description:
Deterioration in left
front walkway



Location:
 7313 US Route 4
 Bridgewater, VT

Photo Taken By:
 Richard Lalancette, P.E.

IMG: 1859

Description:
 Deterioration in right front walkway




Location:
 7313 US Route 4
 Bridgewater, VT

Photo Taken By:
 Richard Lalancette, P.E.

IMG: 1860

Description:
 Well head




Location:
 7313 US Route 4
 Bridgewater, VT

Photo Taken By:
 Richard Lalancette, P.E.

IMG: 1861

Description:
 Deterioration of paving at right side of building




Location:
 7313 US Route 4
 Bridgewater, VT

Photo Taken By:
 Richard Lalancette, P.E.

IMG: 1862

Description:
 Deterioration of paving at rear recreation area




Location:
 7313 US Route 4
 Bridgewater, VT

Photo Taken By:
 Richard Lalancette, P.E.

IMG: 1863

Description:
 Deterioration of paving
 at recreation area




Location:
 7313 US Route 4
 Bridgewater, VT

Photo Taken By:
 Richard Lalancette, P.E.

IMG: 1865

Description:
 Play equipment




Location:
 7313 US Route 4
 Bridgewater, VT

Photo Taken By:
 Richard Lalancette, P.E.

IMG: 1866

Description:
 Deteriorated pedestrian
 paving at left rear of
 building



Location:
 7313 US Route 4
 Bridgewater, VT


Photo Taken By:
 Richard Lalancette, P.E.

IMG: 1867

Description:
 Fence repair needed

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Photo Log
Page 5



Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1868

Description:
Fence repair needed




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1869

Description:
Fence repair needed



Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1870

Description:
Fence repair needed







Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1871


Description:
Fence repair needed

	<p>Location: 7313 US Route 4 Bridgewater, VT</p> <p>Photo Taken By: Richard Lalancette, P.E.</p> <p>IMG: 1872</p> <p>Description: Retainers at play area are leaning</p>		<p>Location: 7313 US Route 4 Bridgewater, VT</p> <p>Photo Taken By: Richard Lalancette, P.E.</p> <p>IMG: 1873</p> <p>Description: Front overhead light and signage</p>
---	--	---	--

	<p>Location: 7313 US Route 4 Bridgewater, VT</p> <p>Photo Taken By: Richard Lalancette, P.E.</p> <p>IMG: 1874</p> <p>Description: Spotlight at right side of building</p>		<p>Location: 7313 US Route 4 Bridgewater, VT</p> <p>Photo Taken By: Richard Lalancette, P.E.</p> <p>IMG: 1875</p> <p>Description: Spotlight at right side of building</p>
--	---	--	---

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Photo Log
Page 7




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1876

Description:
Canopy light at left rear
entry




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1877

Description:
Left rear of building




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1878

Description:
Right side of building




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1879

Description:
Deteriorated roofing at
right bulkhead entry



Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1880

Description:
Deteriorated door at
right bulkhead entry



Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1881

Description:
Electric service to
building



Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1882

Description:
Rot in trim at front
basement windows



Location:
7313 US Route 4
Bridgewater, VT



Photo Taken By:
Richard Lalancette, P.E.

IMG: 1883

Description:
Deteriorated drainage
paving at front of
building

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Photo Log
Page 9

	<p>Location: 7313 US Route 4 Bridgewater, VT</p> <p>Photo Taken By: Richard Lalancette, P.E.</p> <p>IMG: 1885</p> <p>Description: Cracked front entry platform</p>
	<p>Location: 7313 US Route 4 Bridgewater, VT</p> <p>Photo Taken By: Richard Lalancette, P.E.</p> <p>IMG: 1884</p> <p>Description: Rot in trim at front basement windows</p>
	<p>Location: 7313 US Route 4 Bridgewater, VT</p> <p>Photo Taken By: Richard Lalancette, P.E.</p> <p>IMG: 1887</p> <p>Description: Deteriorated drainage paving at front of building</p>
	<p>Location: 7313 US Route 4 Bridgewater, VT</p> <p>Photo Taken By: Richard Lalancette, P.E.</p> <p>IMG: 1886</p> <p>Description: Deteriorated drainage paving at front of building</p>

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Photo Log
Page 10




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1888

Description:
Rot in window sash



Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1889

Description:
Rot in window sash




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1890

Description:
Rot in window sash



Location:
7313 US Route 4
Bridgewater, VT


Photo Taken By:
Richard Lalancette, P.E.

IMG: 1891

Description:
Right bulkhead roof in poor condition

Town of Bridgewater
 Attn: Town Select Board & Ms. Nancy Robinson
 May 27, 2016

Photo Log
 Page 11




Location:
 7313 US Route 4
 Bridgewater, VT

Photo Taken By:
 Richard Lalancette, P.E.

IMG: 1892

Description:
 Right bulkhead roof in
 poor condition



Location:
 7313 US Route 4
 Bridgewater, VT

Photo Taken By:
 Richard Lalancette, P.E.

IMG: 1894

Description:
 Cracked lower trim at
 right entry



Location:
 7313 US Route 4
 Bridgewater, VT

Photo Taken By:
 Richard Lalancette, P.E.

IMG: 1895

Description:
 Underground fuel
 storage tank



Location:
 7313 US Route 4
 Bridgewater, VT



Photo Taken By:
 Richard Lalancette, P.E.


IMG: 1896


Description:
 Propane storage tank

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Photo Log
Page 12

 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1897</p> <p><u>Description:</u> Deteriorated trim</p>	 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1898</p> <p><u>Description:</u> Deteriorated trim</p>
---	---	--	---

 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1899</p> <p><u>Description:</u> Deteriorated trim</p>	 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1900</p> <p><u>Description:</u> Sprinkler connection</p>
--	---	---	--




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1901

Description:
Cracked lower trim




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1902

Description:
Siding repair needed by
right rear entry




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1903

Description:
Deteriorated lower trim






Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.


IMG: 1904

Description:
Deteriorated drip edge
at rear of building

 <p>05/25/2016</p>	<p>Location: 7313 US Route 4 Bridgewater, VT</p> <p>Photo Taken By: Richard Lalancette, P.E.</p> <p>IMG: 1905</p> <p>Description: Add cap at perimeter drain cleanout</p>	 <p>05/25/2016</p>	<p>Location: 7313 US Route 4 Bridgewater, VT</p> <p>Photo Taken By: Richard Lalancette, P.E.</p> <p>IMG: 1906</p> <p>Description: Sloughing of left rear bank</p>
 <p>05/25/2016</p>	<p>Location: 7313 US Route 4 Bridgewater, VT</p> <p>Photo Taken By: Richard Lalancette, P.E.</p> <p>IMG: 1907</p> <p>Description: Damaged lower trim at left rear of building</p>	 <p>05/25/2016</p>	<p>Location: 7313 US Route 4 Bridgewater, VT</p> <p>Photo Taken By: Richard Lalancette, P.E.</p> <p>IMG: 1908</p> <p>Description: Left rear entry has heaved and settled</p>

Town of Bridgewater
 Attn: Town Select Board & Ms. Nancy Robinson
 May 27, 2016

Photo Log
 Page 15




Location:
 7313 US Route 4
 Bridgewater, VT

Photo Taken By:
 Richard Lalancette, P.E.

IMG: 1909

Description:
 Left rear entry has
 heaved and settled




Location:
 7313 US Route 4
 Bridgewater, VT

Photo Taken By:
 Richard Lalancette, P.E.

IMG: 1911

Description:
 Left rear entry has
 heaved and settled




Location:
 7313 US Route 4
 Bridgewater, VT

Photo Taken By:
 Richard Lalancette, P.E.

IMG: 1912

Description:
 Crack in foundation at
 left rear of building



Location:
 7313 US Route 4
 Bridgewater, VT


Photo Taken By:
 Richard Lalancette, P.E.

IMG: 1913

Description:
 Low spots in grade

Town of Bridgewater
 Attn: Town Select Board & Ms. Nancy Robinson
 May 27, 2016

Photo Log
 Page 16




Location:
 7313 US Route 4
 Bridgewater, VT

Photo Taken By:
 Richard Lalancette, P.E.

IMG: 1914

Description:
 Basement window in
 poor condition / No
 storm window




Location:
 7313 US Route 4
 Bridgewater, VT

Photo Taken By:
 Richard Lalancette, P.E.

IMG: 1915

Description:
 Basement window in
 poor condition / No
 storm window




Location:
 7313 US Route 4
 Bridgewater, VT

Photo Taken By:
 Richard Lalancette, P.E.

IMG: 1916

Description:
 Gable vent





Location:
 7313 US Route 4
 Bridgewater, VT



Photo Taken By:
 Richard Lalancette, P.E.

IMG: 1918

Description:
 Damaged trim at newer
 window





Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016


	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1919</p> <p><u>Description:</u> Damaged trim at left rear window</p>		<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1920</p> <p><u>Description:</u> Deterioration of soffit trim</p>
---	--	---	--

	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1921</p> <p><u>Description:</u> Deterioration of soffit trim</p>		<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1922</p> <p><u>Description:</u> Damaged roofing</p>
--	--	--	---

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Photo Log
Page 18

 <p>05/25/2016</p>	<p>Location: 7313 US Route 4 Bridgewater, VT</p> <p>Photo Taken By: Richard Lalancette, P.E.</p> <p>IMG: 1923</p> <p>Description: Deteriorated trim at newer window</p>	<p>Location: 7313 US Route 4 Bridgewater, VT</p> <p>Photo Taken By: Richard Lalancette, P.E.</p> <p>IMG: 1924</p> <p>Description: Deteriorated soffit trim</p>	 <p>05/25/2016</p>
 <p>05/25/2016</p>	<p>Location: 7313 US Route 4 Bridgewater, VT</p> <p>Photo Taken By: Richard Lalancette, P.E.</p> <p>IMG: 1925</p> <p>Description: Rot in corner trim</p>	<p>Location: 7313 US Route 4 Bridgewater, VT</p> <p>Photo Taken By: Richard Lalancette, P.E.</p> <p>IMG: 1926</p> <p>Description: Roof over right front entry</p>	 <p>05/25/2016</p>




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1927

Description:
Standing seam metal
roof




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1928

Description:
Trim spray foam
insulation




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1929

Description:
Roof repair needed at
front valley





Location:
7313 US Route 4
Bridgewater, VT


Photo Taken By:
Richard Lalancette, P.E.

IMG: 1930

Description:
Chimney above roof

	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1931</p> <p><u>Description:</u> Roof repair needed at front valley</p>		<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1932</p> <p><u>Description:</u> Seam opening on rear membrane roof</p>
---	--	--	--

	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1933</p> <p><u>Description:</u> Seam opening on rear membrane roof</p>		<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1934</p> <p><u>Description:</u> Rear membrane roof in poor condition</p>
--	--	---	--




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1935

Description:
Loose patch at rear
membrane roof




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1936

Description:
Loose patch at rear
membrane roof




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1937

Description:
Fire alarm panel





Location:
7313 US Route 4
Bridgewater, VT



Photo Taken By:
Richard Lalancette, P.E.

IMG: 1939

Description:
Multipurpose room


Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1940</p> <p><u>Description:</u> Tile repair needed at multipurpose room</p>		<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1941</p> <p><u>Description:</u> Leakage on ceiling at multipurpose</p>
---	---	--	--

	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1942</p> <p><u>Description:</u> Leakage on ceiling at multipurpose room</p>		<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1943</p> <p><u>Description:</u> Leakage on ceiling at multipurpose room</p>
--	---	---	---

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

Photo Log
Page 23



Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1944

Description:
Ceiling tile repair
needed in lower storage
closet




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1946

Description:
Evidence of moisture
entry in kitchen




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1947

Description:
Evidence of moisture
entry in kitchen











Location:
7313 US Route 4
Bridgewater, VT



Photo Taken By:
Richard Lalancette, P.E.



IMG: 1948

Description:
Baseboard enclosure
repair needed


 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1949</p> <p><u>Description:</u> Baseboard enclosure repair needed</p>	 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1950</p> <p><u>Description:</u> Baseboard enclosure repair needed</p>
 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1951</p> <p><u>Description:</u> Waste pump for janitor sink</p>	 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1952</p> <p><u>Description:</u> Mold on wall near janitor's sink</p>

	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1953</p> <p><u>Description:</u> Waste pump for kitchen sink</p>		<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1954</p> <p><u>Description:</u> Deteriorated door</p>
	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1955</p> <p><u>Description:</u> Deteriorated door</p>		<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1956</p> <p><u>Description:</u> Kitchen area</p>

 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1957</p> <p><u>Description:</u> Kitchen area</p>	 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1959</p> <p><u>Description:</u> Left bulkhead entry</p>
---	--	---	---

 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1960</p> <p><u>Description:</u> Heating unit</p>	 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1961</p> <p><u>Description:</u> Indirect water heater</p>
--	--	--	---

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1963

Description:
Heating unit #2




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1965

Description:
Corrosion at relief valve
on water heater




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1967

Description:
Pump for sprinkler
system





Location:
7313 US Route 4
Bridgewater, VT



Photo Taken By:
Richard Lalancette, P.E.

IMG: 1969


Description:
Water pumping
equipment

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016


 <p>05/25/2016</p>	<p>Location: 7313 US Route 4 Bridgewater, VT</p> <p>Photo Taken By: Richard Lalancette, P.E.</p> <p>IMG: 1971</p> <p>Description: Interior finish removed</p>	 <p>05/25/2016</p>	<p>Location: 7313 US Route 4 Bridgewater, VT</p> <p>Photo Taken By: Richard Lalancette, P.E.</p> <p>IMG: 1970</p> <p>Description: Sediment and ultraviolet filters</p>
---	---	---	--

 <p>05/25/2016</p>	<p>Location: 7313 US Route 4 Bridgewater, VT</p> <p>Photo Taken By: Richard Lalancette, P.E.</p> <p>IMG: 1973</p> <p>Description: Ceiling tile repair needed</p>	 <p>05/25/2016</p>	<p>Location: 7313 US Route 4 Bridgewater, VT</p> <p>Photo Taken By: Richard Lalancette, P.E.</p> <p>IMG: 1972</p> <p>Description: Interior finish in poor condition</p>
--	--	--	---

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1974</p> <p><u>Description:</u> Interior finish in poor condition</p>	 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1975</p> <p><u>Description:</u> Evidence of leakage in front basement</p>
 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1976</p> <p><u>Description:</u> Wall crack in basement</p>	 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1977</p> <p><u>Description:</u> Wall crack in basement</p>

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1978

Description:
Elevator equipment




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1980

Description:
Interior finish repair
needed



Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1981

Description:
Rot in lower plate of
interior basement wall





Location:
7313 US Route 4
Bridgewater, VT



Photo Taken By:
Richard Lalancette, P.E.

IMG: 1982

Description:
Interior finish repair
needed

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

 A black and white photograph showing a corner of a room. The wall is light-colored and has a large, irregular hole or missing section of plaster. A window frame is visible on the right side. A date stamp '05/25/2016' is in the bottom right corner.	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1983</p> <p><u>Description:</u> Interior finish repair needed</p>	 A black and white photograph of a window. The window pane is cracked and appears to be broken or severely damaged. The frame is dark. A date stamp '05/25/2016' is in the bottom right corner.	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1984</p> <p><u>Description:</u> Cracked window pane (one of many)</p>
---	---	---	---

 A black and white photograph of a wall. There are several holes and areas of missing plaster. One hole is particularly large and irregular. A date stamp '05/25/2016' is in the bottom right corner.	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1985</p> <p><u>Description:</u> Plaster repair needed</p>	 A black and white photograph of a ceiling. The surface is light-colored and shows signs of wear and deterioration, including a small dark spot. A date stamp '05/25/2016' is in the bottom right corner.	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1986</p> <p><u>Description:</u> Deterioration of tin ceiling</p>
---	---	--	--


Town of Bridgewater

Attn: Town Select Board & Ms. Nancy Robinson

May 27, 2016

Photo Log

Page 32




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1987

Description:
Typical classroom




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1988

Description:
Upper front hall




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1989

Description:
Leakage on ceiling





Location:
7313 US Route 4
Bridgewater, VT



Photo Taken By:
Richard Lalancette, P.E.

IMG: 1990



Description:
Tile ceiling has been
patched


Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1991</p> <p><u>Description:</u> Tile ceiling needs repair</p>	 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1992</p> <p><u>Description:</u> Evidence of leakage on ceiling</p>
---	---	--	--


 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1993</p> <p><u>Description:</u> Auxiliary service panel</p>	 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1994</p> <p><u>Description:</u> Interior of auxiliary panel</p>
--	---	---	---

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1995</p> <p><u>Description:</u> Right rear entry</p>	 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1996</p> <p><u>Description:</u> Cracked interior window</p>
---	--	--	---

 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1997</p> <p><u>Description:</u> Upper attic / Knob and tube wiring</p>	 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 1998</p> <p><u>Description:</u> Upper attic / Knob and tube wiring</p>
--	--	---	--

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 1999

Description:
Left truss has been braced




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 2000

Description:
Right truss in attic is leaning




Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 2002

Description:
Repair air handler system in attic





Location:
7313 US Route 4
Bridgewater, VT

Photo Taken By:
Richard Lalancette, P.E.

IMG: 2003

Description:
Heating coil in air handling system

Town of Bridgewater
Attn: Town Select Board & Ms. Nancy Robinson
May 27, 2016

 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 2004</p> <p><u>Description:</u> Center attic</p>	 <p>05/25/2016</p>	<p><u>Location:</u> 7313 US Route 4 Bridgewater, VT</p> <p><u>Photo Taken By:</u> Richard Lalancette, P.E.</p> <p><u>IMG:</u> 2005</p> <p><u>Description:</u> Center attic</p>
---	--	--	--

INSPECTION CHECK LIST

Date: 5/25/2016 Job #: 16-36926 Weather: FAIR 60°F Page 1 of
Inspected by: Richard Lalancette, P.E. Present: ACCESS BY OWNER
For: Town of Bridgewater Attn: Town Select Board & Ms. Nancy Robinson Location: (Your) Bridgewater Village School 7313 US Route 4 Bridgewater, VT 05034

I. OUTSIDE

- 1. Ground Slope: Good Fair Poor ; Low Spots: Yes
2. No. Elec. Wires: 3 Over Under Main
3. Termites: None apparent Evidences of Insects or rot:
4. Cracks in Foundation Wall: Yes NV Foundation Insulation? Yes No
5. Exterior Walls: Brick Wood Siding Wood/Asbestos Shingles Stucco/Stone Aluminum Vinyl TI-II Composite Claps
6. Roof: Asphalt Shingles Slate Wood Shingles/Shakes Built-Up Membrane SS Metal Cor Metal Rolled
7. Gutters & Leaders: PVC Aluminum Galv. Copper Wood None Drains/Dry Wells: Yes No Condition: Good Fair Poor
8. Putty: Serviceable Required Panes Cracked: Yes No Not Visible ; Window Repairs?
9. Stormsash: Wood Alum. Wood & Alum. Steel None Not All Thermal panes Needed on Non-Thermo pane Fixed Panes
10. Exterior Paint or Stain: Good Fair Poor Trim Paint or Stain: Good Fair Poor needed:
11. Caulking: Serviceable Required at: Chimney; Diff. Mat. Windows/doors; other
12. Trim Repairs/Replacement needed: Yes No Explain:
13. Wall Insulation: None Apparent Evidence of 3" 6" Type Other Comments:

II. BASEMENT/UTILITY ROOM/CRAWL AREA; MECHANICAL/ELECTRICAL

- 1. Finished/ insulated? Full? Part? Walls Ceilings Sill Pockets Other: Hand Rail at stair; Y N
2. Walls: Concrete Block Stone Others Good Fair Poor ; Cracks/ Mvmt: Yes No
3. Evidence of Moisture-Seepage Penetration: Yes No NV ; WS on Walls Floor Wood at bulkhead;
4. Floor: Concrete Dirt Other ; Good Fair Poor ; Cracks Badly Cracked NV
5. Termites/ Insects/Sill Rot: None apparent Evidences of:
6. Framing: Platform Balloon Post and Beam Log Other: Floor Joist span wall to wall?
6. Columns: Steel Temp Steel Wood Block/Brick Chimney Corbel Other None Bearing Wall Few Visible Not Visible
7. Girders: Steel Wood None/Bearing Wall (Not) (Part) Visible Condition: Good Fair Poor
8. Floor Joints: Size & Spacing 2x10x16 ; (Not) (Few) Visible Condition: Good Fair Poor
9. Heating System: Oil Gas Electric Hot Water Steam Hot Air Make His Service (2 units) Age 1969/1990 Net IBR?
10. Central Air System Make: Tons: Age: Condenser Location Operating: Yes No Network Insulated: Yes No
11. Hot Water System: Instant w/Heating System Tankless Indirect Gas Elec. Oil Make Fours 1991 Gals. Relief Ext
12. Plumbing: Copper PEX Brass Galv. Iron ; Condition G F P Repair Indicated: Yes No
13. DWV material: PVC ABS Iron CL CU Lead ; Condition G F P Repair Indicated: Yes No
14. Electric: Panel Location 5582 Main: Yes No Amperes 200 Circuit 54 Voltage: 120/240 120 ; Breakers Fuses
AL SE CU SE Pointed Screws Openings Double Tapped Breakers Circuits over fused All branch Circuits
Wiring is: Adequate Just Adequate Inadequate Other: Part 1200

TRUSS IN RAFTER DISTURBS TRUSS HOW CARRIES BEARING AND RAFTERS ALSO NOTED

III. ATTIC AREA (Access Location: Attic Room)

- 1. Roof Rafters: Size/Spacing 4x6/2x12 Rafters Floor Joists: Size/Spacing 2x8s Comments:
2. Insulation: Floor 4 Walls Ceiling None Not Visible ; Good Adeq Inadeq 3. Flooring: Yes No Partial
4. Ventilation: Ridge Soffit Gable Roof None Pro-pavent: Yes No Adequate: Yes No
5. Access: Serviceable Poor None ; 6. Windows: No 3 7. Roof leaks: None apparent Evidence of Part

IV. REMARKS AND SUGGESTIONS

V. OTHER

Apparent good chimney lower than air
Gyro tanker missing screws on
Low slope in kitchen roof/attic and beam
Dampness lower level of kitchen
Plumbing lower kitchen drain and sink
Dampness in front porch/masonry structure

1. Water: Private Well Loc: Front Municipal
Pump Equip Sediment Filter Softener Other
2. Waste Disposal: Private Syst Loc: Municipal
Rutland Drain cover with cap
Black sun cover
Rothman's plumbing
L.A. O'Neil's plumbing from 12/17/14
Missing screws on

SUPPLEMENTAL II INSPECTION CHECK LIST

Date: 5/25/2016

Job #: 16-36926/Town of Bridgewater

Engineer: Richard Lalancette, P.E.

Page ___ of ___

1. Describe Project Location: _____ AppendMap: _____
2. Total no. buildings 1 No. units _____ H'cap _____ 4 br _____ 3 br _____ 2 br _____ 1 br _____
3. Type of project: Family housing _____ Elderly Housing _____ Other SCHOOL
4. Site Utilities: Water: Municipal _____ On site Sewer: Municipal On site _____
Describe system/Equipment _____
5. Site Access from what street(s): Route 4 Surface Type Condition: G _____ F _____ P _____
6. Parking Areas: Surface Type: ASPHALT Condition: G _____ F _____ P _____ No. Vehicles: 1-2
Curbs: _____ Marking: _____ Drains: _____ No. Designated H'cap: 0 Van Accessible: _____
7. Sidewalks/Walkways: Surfacing type: ASPHALT Condition: G _____ F _____ P
8. Site Drainage: Describe _____ Condition: G _____ F _____ P _____
Maintenance Needed: _____
9. Site Lighting: Freestanding _____ No. _____ Condition: G _____ F _____ P _____ Location: _____
Building mounted: 4 No. _____ Condition: G _____ F P _____ Location: _____
10. Project Signage: Describe Location @ STREET / BUILDING FRONT Size: _____ Condition: G _____ F P _____
12. Fencing: Describe type 6' - Chain Link Linear feet _____ Condition: G _____ F P _____
12. Mailboxes: Describe _____ Accessible: _____ Access Route: _____ Condition: G _____ F _____ P _____
13. Playground Equip: Describe TWO SLIDES / SWING Accessible: NO Accessible Route _____ Condition: G _____ F P _____
14. Dumpsters: Location _____ Pad: G _____ F _____ P _____ Enclosure: G _____ F _____ P _____
15. Other Amenities: Describe _____
16. Accessible Routes: Describe _____
Deficiencies _____
17. Personnel interviewed: _____ Date: _____
18. Date of last rehab: _____ Improvements/Replacements: _____

19. Current Reserve Balance _____ Annual Contribution _____
20. Planned Rehabilitation/ Improvements _____

21. Any commitment of 3rd party funding _____
22. Other: _____

NOTICE SIDE ROUTE 4 BRIDGEWAY
FRONT BRIDGEWAY FACES SOUTH
1 ACCESS DRIVE FROM ROUTE 4 / FRONT
SILVERWOOD & ROAD
ASPHALT DRIVE @ FRONT / POOL / CHAIN LINK / SIDEWALK / OVERPASS
WOOD @ R/F SUPPLY TOWER BRIDGE
PAVED DRIVE CONCRETE PROGRESS PAVEMENT / F-P / CHAIN LINK / SIDEWALK
SUBSTANTIAL AREA @ ROAD / F-P / CHAIN LINK / SIDEWALK
POD DRIVE @ LOT F-P
FOUR PLAY AREA @ LOT / FENCE / FENCE / PLAY AREA / DAMAGED / DRIVE
TWO PLAY AREA @ PLAY AREA / WALKWAY / DRIVE
STU FAMILY PLAY AREA SIDE DRIVE TO EAST
HILL SIDE @ DRIVE DRIVE SOUTH
WEST SIDE DRIVE SOUTH

1 - CONCRETE WALKWAY @ FRONT
2 - DRIVE MID ISLAND @ WEST
1 - CONCRETE DRIVE @ WEST

ROOM-BY-ROOM INSPECTION CHECK LIST

Date: 5/25/2016

Job #: 16-36926/Town of Bridgewater

Engineer: Richard Lalancette, P.E.

Page 2 of

Water on Water off

ROOM: Lower Level Multi Purpose Room / Kitchen / Storage

- 1. Ceiling: Plaster Sheetrock Other T111 Papered Painted
Cracked: Yes No ; Evidence of Leak: YES Leak on Wall Ceiling Investigate
2. Walls: Plaster Sheetrock Tile Other PTD Ceilings Papered Painted
3. Windows: No. 6 ; Weatherstripped: Yes No ; Cords Broken: Yes Adeq. Egress
4. Electric outlets: Number 20 ; NO GFI BY KS
5. Floor: Wood Tile Vinyl Carpet Condition: Good Fair Poor ; Slope: Yes No
6. Trim: Wood Tile Steel Condition: Good Fair Poor ;
7. Hardware (locks, knobs, etc.): Condition: Good Serviceable Poor ;
8. Heating Number 2 ; Radiators Convectors Grills Baseboard Rad. H't'g Pipe Riser
9. Doors: Exter. 0 Weatherstripped: Yes No Cond.: Good Fair Poor ; Need Adj./Repair: Yes
Interior 6 Condition: Good Fair Poor ; Need Adj./Repair: Yes
10. Plumbing fixtures: Yes No ; Good Operating Poor Faucet Leak: Yes
Pressure: Normal Below Normal ; Grouting needed at Tub/Shower Tile: Yes
12. Cabinets: Kitchen Medicine None
12. Stove N (Gas Elec.) ; Refrigerator MD None ; Good Operating Old
13. Fireplace: Yes No ; Not Tested ; Appears: Serviceable ; Poor Repair Damper: Yes
COMMON T111 ROOM NEAR SWIMMING POOL FOR PATRON USE DRAINAGE DOORS @ KITCHEN
MISSING LIT COVERS SWIMMING POOL FOR KITCHEN USE SHOOTERS SWIM FACILITY COVER
EVIDENCE OF SURFACE @ KITCHEN WALL MOULD BY WINDOW SIDE PUMP @ KITCHEN DRAIN FROM BATH
DRAIN @ BATH WALL SWIMMING POOL FACILITY SIDE SWIMMING POOL FACILITY SIDE

is on outside

ROOM: Front Storage Room

- 1. Ceiling: Plaster Sheetrock Other T111 Papered Painted
Cracked: Yes No ; Evidence of Leak: YES Leak on Wall Ceiling Investigate
2. Walls: Plaster Sheetrock Tile Other Papered Painted
3. Windows: No. 0 ; Weatherstripped: Yes No ; Cords Broken: Yes Adeq. Egress
4. Electric outlets: Number 0 ;
5. Floor: Wood Tile Vinyl Carpet Condition: Good Fair Poor ; Slope: Yes
6. Trim: Wood Tile Steel Condition: Good Fair Poor ;
7. Hardware (locks, knobs, etc.): Condition: Good Serviceable Poor ;
8. Heating Number 0 ; Radiators Convectors Grills Baseboard Rad. H't'g Pipe Riser
9. Doors: Exter. 0 Weatherstripped: Yes No Cond.: Good Fair Poor ; Need Adj./Repair: Yes
Interior 1 Condition: Good Fair Poor ; Need Adj./Repair: Yes
10. Plumbing fixtures: Yes No ; Good Operating Poor Faucet Leak: Yes
Pressure: Normal Below Normal ; Grouting needed at Tub/Shower Tile: Yes
12. Cabinets: Kitchen Medicine None
12. Stove (Gas Elec.) ; Refrigerator None ; Good Operating Old
13. Fireplace: Yes No ; Not Tested ; Appears: Serviceable ; Poor Repair Damper: Yes
COMMON T111 ROOM

ROOM: Right Classroom

- 1. Ceiling: Plaster Sheetrock Other T111 Papered Painted
Cracked: Yes No ; Evidence of Leak: YES Leak on Wall Ceiling Investigate
2. Walls: Plaster Sheetrock Tile Other Papered Painted
3. Windows: No. 5 ; Weatherstripped: Yes No ; Cords Broken: Yes Adeq. Egress 7 Doors
4. Electric outlets: Number 8 ; CORD BY SWIM
5. Floor: Wood Tile Vinyl Carpet Condition: Good Fair Poor ; Slope: Yes
6. Trim: Wood Tile Steel Condition: Good Fair Poor ;
7. Hardware (locks, knobs, etc.): Condition: Good Serviceable Poor ;
8. Heating Number 2 ; Radiators Convectors Grills Baseboard Rad. H't'g Pipe Riser
9. Doors: Exter. 1 Weatherstripped: Yes No Cond.: Good Fair Poor ; Need Adj./Repair: Yes
Interior 2 Condition: Good Fair Poor ; Need Adj./Repair: Yes
10. Plumbing fixtures: Yes No ; Good Operating Poor Faucet Leak: Yes
Pressure: Normal Below Normal ; Grouting needed at Tub/Shower Tile: Yes
12. Cabinets: Kitchen Medicine None
12. Stove (Gas Elec.) ; Refrigerator None ; Good Operating Old
13. Fireplace: Yes No ; Not Tested ; Appears: Serviceable ; Poor Repair Damper: Yes
COMMON T111 ROOM
COMMON T111 ROOM
COMMON T111 ROOM
COMMON T111 ROOM

ROOM-BY-ROOM INSPECTION CHECK LIST

Date: 5/25/2016

Job #: 16-36926/Town of Bridgewater

Engineer: Richard Lalancette, P.E.

Page 3 of 3

Water on _____ Water off _____

ROOM: RF UNSTRY / STAIR

1. Ceiling: Plaster _____ Sheetrock Other _____ Papered _____ Painted _____
Cracked: Yes _____ No ; Evidence of Leak: NO Leak on Wall _____ Ceiling Investigate _____
 2. Walls: Plaster _____ Sheetrock Tile _____ Other CONCRETE Papered _____ Painted _____
 3. Windows: No. 0 ; Weatherstripped: Yes _____ No _____ ; Cords Broken: Yes _____ Adeq. Egress _____
 4. Electric outlets: Number 0 ;
 5. Floor: Wood _____ Tile _____ Vinyl _____ Carpet Condition: Good _____ Fair Poor _____ ; Slope: Yes _____
 6. Trim: Wood Tile _____ Steel _____ Condition: Good _____ Fair Poor _____ ;
 7. Hardware (locks, knobs, etc.): Condition: Good _____ Serviceable Poor _____ ;
 8. Heating Number 0 ; Radiators _____ Convectors _____ Grills _____ Baseboard _____ Rad. H'g _____ Pipe Riser _____
 9. Doors: Exter. 1 Weatherstripped: Yes _____ No _____ Cond.: Good _____ Fair _____ Poor _____ ; Need Adj./Repair: Yes _____
Interior 1 Condition: Good _____ Fair _____ Poor _____ ; Need Adj./Repair: Yes _____
 10. Plumbing fixtures: Yes _____ No ; Good _____ Operating _____ Poor _____ Faucet Leak: Yes _____
Pressure: Normal _____ Below Normal _____ ; Grouting needed at Tub/Shower Tile: Yes _____
 12. Cabinets: Kitchen _____ Medicine _____ None
 12. Stove _____ (Gas _____ Elec. _____) ; Refrigerator _____ None ; Good _____ Operating _____ Old _____
 13. Fireplace: Yes _____ No ; Not Tested _____ ; Appears: Serviceable _____ ; Poor _____ Repair Damper: Yes _____
- DOOR UNDER REPAIR

ROOM: R. STRUWAY AND HALL

1. Ceiling: Plaster _____ Sheetrock Other TRU Papered _____ Painted _____
Cracked: Yes _____ No ; Evidence of Leak: HALL Leak on Wall _____ Ceiling Investigate
 2. Walls: Plaster _____ Sheetrock Tile _____ Other _____ Papered _____ Painted _____
 3. Windows: No. 0 ; Weatherstripped: Yes _____ No _____ ; Cords Broken: Yes _____ Adeq. Egress _____
 4. Electric outlets: Number 0 ;
 5. Floor: Wood _____ Tile _____ Vinyl SPRAY Carpet Condition: Good _____ Fair Poor _____ ; Slope: Yes NO
 6. Trim: Wood Tile _____ Steel _____ Condition: Good _____ Fair Poor _____ ;
 7. Hardware (locks, knobs, etc.): Condition: Good _____ Serviceable _____ Poor _____ ;
 8. Heating Number _____ ; Radiators _____ Convectors _____ Grills _____ Baseboard _____ Rad. H'g _____ Pipe Riser _____
 9. Doors: Exter. 0 Weatherstripped: Yes _____ No _____ Cond.: Good _____ Fair _____ Poor _____ ; Need Adj./Repair: Yes _____
Interior 2 Condition: Good _____ Fair _____ Poor _____ ; Need Adj./Repair: Yes NO
 10. Plumbing fixtures: Yes _____ No ; Good _____ Operating _____ Poor _____ Faucet Leak: Yes _____
Pressure: Normal _____ Below Normal _____ ; Grouting needed at Tub/Shower Tile: Yes _____
 12. Cabinets: Kitchen _____ Medicine _____ None
 12. Stove _____ (Gas _____ Elec. _____) ; Refrigerator _____ None ; Good _____ Operating _____ Old _____
 13. Fireplace: Yes _____ No ; Not Tested _____ ; Appears: Serviceable _____ ; Poor _____ Repair Damper: Yes _____
- MISSED WORK @ W/O STAIR

ROOM: L. STONE & HALL

1. Ceiling: Plaster _____ Sheetrock Other TRU Papered _____ Painted _____
Cracked: Yes _____ No ; Evidence of Leak: YES Leak on Wall _____ Ceiling Investigate _____
 2. Walls: Plaster _____ Sheetrock Tile _____ Other _____ Papered _____ Painted _____
 3. Windows: No. 0 ; Weatherstripped: Yes _____ No _____ ; Cords Broken: Yes _____ Adeq. Egress _____
 4. Electric outlets: Number 3 ; SABON
 5. Floor: Wood SPRAY Tile _____ Vinyl _____ Carpet _____ Condition: Good _____ Fair Poor _____ ; Slope: Yes
 6. Trim: Wood Tile _____ Steel _____ Condition: Good _____ Fair Poor _____ ;
 7. Hardware (locks, knobs, etc.): Condition: Good _____ Serviceable _____ Poor _____ ;
 8. Heating Number 0 ; Radiators _____ Convectors _____ Grills _____ Baseboard _____ Rad. H'g _____ Pipe Riser _____
 9. Doors: Exter. 0 Weatherstripped: Yes NO No _____ Cond.: Good _____ Fair PO Poor _____ ; Need Adj./Repair: Yes NO
Interior 4 Condition: Good _____ Fair _____ Poor _____ ; Need Adj./Repair: Yes _____
 10. Plumbing fixtures: Yes _____ No ; Good _____ Operating _____ Poor _____ Faucet Leak: Yes _____
Pressure: Normal _____ Below Normal _____ ; Grouting needed at Tub/Shower Tile: Yes _____
 12. Cabinets: Kitchen _____ Medicine _____ None
 12. Stove _____ (Gas _____ Elec. _____) ; Refrigerator _____ None ; Good _____ Operating _____ Old _____
 13. Fireplace: Yes _____ No ; Not Tested _____ ; Appears: Serviceable _____ ; Poor _____ Repair Damper: Yes _____
- CONCRETE WORK @ STAIR
REPAIR WORK @ STAIR
W/O STAIR

ROOM-BY-ROOM INSPECTION CHECK LIST

Date: 5/25/2016

Job #: 16-36926/Town of Bridgewater

Engineer: Richard Lalancette, P.E.

Page 4 of 4

Water on _____ Water off _____

ROOM: Running Room

1. Ceiling: Plaster _____ Sheetrock _____ Other TLW Papered _____ Painted _____
Cracked: Yes _____ No ; Evidence of Leak: YES Leak on Wall _____ Ceiling _____ Investigate:
2. Walls: Plaster _____ Sheetrock _____ Tile _____ Other _____ Papered _____ Painted _____
3. Windows: No. 1 ; Weatherstripped: Yes _____ No ; Cords Broken: Yes Adeq. Egress _____
4. Electric outlets: Number 3 ; SATUR ON
5. Floor: Wood _____ Tile _____ Vinyl _____ Carpet ISOPAKY Condition: Good _____ Fair _____ Poor _____ ; Slope: Yes
6. Trim: Wood _____ Tile _____ Steel _____ Condition: Good _____ Fair _____ Poor _____ ;
7. Hardware (locks, knobs, etc.): Condition: Good _____ Serviceable _____ Poor _____ ;
8. Heating Number 1 ; Radiators _____ Convectors _____ Grills _____ Baseboard _____ Rad. H't'g _____ Pipe Riser _____
9. Doors: Exter. 0 Weatherstripped: Yes _____ No _____ Cond.: Good _____ Fair _____ Poor _____ ; Need Adj./Repair: Yes _____
Interior 0 Condition: Good _____ Fair _____ Poor _____ ; Need Adj./Repair: Yes _____
10. Plumbing fixtures: Yes _____ No ; Good _____ Operating _____ Poor _____ Faucet Leak: Yes _____
Pressure: Normal _____ Below Normal _____ ; Grouting needed at Tub/Shower Tile: Yes _____
12. Cabinets: Kitchen _____ Medicine _____ None
12. Stove _____ (Gas _____ Elec. _____) ; Refrigerator _____ None ; Good _____ Operating _____ Old _____
13. Fireplace: Yes _____ No ; Not Tested _____ ; Appears: Serviceable _____ ; Poor _____ Repair Damper: Yes _____
TLW can Repair
Wash Repair
NOSSUR-FRM

ROOM: Storage Room

1. Ceiling: Plaster _____ Sheetrock _____ Other TLW Papered _____ Painted _____
Cracked: Yes _____ No ; Evidence of Leak: YES Leak on Wall _____ Ceiling _____ Investigate:
2. Walls: Plaster _____ Sheetrock _____ Tile _____ Other _____ Papered _____ Painted _____
3. Windows: No. 2 ; Weatherstripped: Yes _____ No ; Cords Broken: Yes Adeq. Egress _____
4. Electric outlets: Number 1 ; CRUT. UNDER
5. Floor: Wood COVERED Vinyl _____ Carpet _____ Condition: Good _____ Fair _____ Poor ; Slope: Yes _____
6. Trim: Wood _____ Tile _____ Steel _____ Condition: Good _____ Fair _____ Poor _____ ;
7. Hardware (locks, knobs, etc.): Condition: Good _____ Serviceable _____ Poor _____ ;
8. Heating Number 1 ; Radiators _____ Convectors _____ Grills _____ Baseboard _____ Rad. H't'g _____ Pipe Riser _____
9. Doors: Exter. 0 Weatherstripped: Yes _____ No _____ Cond.: Good _____ Fair _____ Poor _____ ; Need Adj./Repair: Yes _____
Interior 0 Condition: Good _____ Fair _____ Poor _____ ; Need Adj./Repair: Yes _____
10. Plumbing fixtures: Yes _____ No ; Good _____ Operating _____ Poor _____ Faucet Leak: Yes _____
Pressure: Normal _____ Below Normal _____ ; Grouting needed at Tub/Shower Tile: Yes _____
12. Cabinets: Kitchen _____ Medicine _____ None
12. Stove _____ (Gas _____ Elec. _____) ; Refrigerator _____ None ; Good _____ Operating _____ Old _____
13. Fireplace: Yes _____ No ; Not Tested _____ ; Appears: Serviceable _____ ; Poor _____ Repair Damper: Yes _____
DAMAGED W. TLW
DAMAGED SR
DO NOT REPAIR

ROOM: MTV's Room

1. Ceiling: Plaster _____ Sheetrock _____ Other TLW Papered _____ Painted _____
Cracked: Yes _____ No ; Evidence of Leak: YES Leak on Wall _____ Ceiling _____ Investigate: _____
2. Walls: Plaster _____ Sheetrock _____ Tile _____ Other FOUR Papered _____ Painted _____
3. Windows: No. 2 ; Weatherstripped: Yes _____ No ; Cords Broken: Yes Adeq. Egress _____
4. Electric outlets: Number 1 ; CAT 6
5. Floor: Wood _____ Tile _____ Vinyl _____ Carpet _____ Condition: Good _____ Fair TLW Poor _____ ; Slope: Yes
6. Trim: Wood _____ Tile _____ Steel _____ Condition: Good _____ Fair _____ Poor _____ ;
7. Hardware (locks, knobs, etc.): Condition: Good _____ Serviceable _____ Poor _____ ;
8. Heating Number 1 ; Radiators _____ Convectors _____ Grills _____ Baseboard _____ Rad. H't'g _____ Pipe Riser _____
9. Doors: Exter. 0 Weatherstripped: Yes _____ No _____ Cond.: Good _____ Fair _____ Poor _____ ; Need Adj./Repair: Yes _____
Interior 0 Condition: Good _____ Fair _____ Poor _____ ; Need Adj./Repair: Yes _____
10. Plumbing fixtures: Yes _____ No ; Good _____ Operating _____ Poor _____ Faucet Leak: Yes _____
Pressure: Normal Below Normal _____ ; Grouting needed at Tub/Shower Tile: Yes _____
12. Cabinets: Kitchen _____ Medicine _____ None _____
12. Stove _____ (Gas _____ Elec. _____) ; Refrigerator _____ None ; Good _____ Operating _____ Old _____
13. Fireplace: Yes _____ No ; Not Tested _____ ; Appears: Serviceable _____ ; Poor _____ Repair Damper: Yes _____
W. TLW REPAIR
2 STAIR / 2 WEMPA / 2 SWIR
2 SWIR REPAIR ROOM

ROOM-BY-ROOM INSPECTION CHECK LIST

Date: 5/25/2016

Job #: 16-36926/Town of Bridgewater

Engineer: Richard Lalancette, P.E.

Page 5 of 5

Water on _____ Water off _____

ROOM: LADY'S ROOM

1. Ceiling: Plaster _____ Sheetrock _____ Other FWS Papered _____ Painted _____
Cracked: Yes _____ No ; Evidence of Leak: NO Leak on Wall _____ Ceiling Investigate
2. Walls: Plaster _____ Sheetrock _____ Tile _____ Other FRONT Papered _____ Painted _____
3. Windows: No. 0; Weatherstripped: Yes _____ No ; Cords Broken: Yes _____ Adeq. Egress _____
4. Electric outlets: Number 1; BATH GFS/POTRIP
5. Floor: Wood _____ Tile Vinyl _____ Carpet _____ Condition: Good _____ Fair Poor _____; Slope: Yes
6. Trim: Wood _____ Tile _____ Steel _____ Condition: Good _____ Fair Poor _____;
7. Hardware (locks, knobs, etc.): Condition: Good _____ Serviceable Poor _____;
8. Heating Number 1; Radiators _____ Convectors _____ Grills _____ Baseboard Rad. H't'g _____ Pipe Riser _____
9. Doors: Exter. 0 Weatherstripped: Yes _____ No _____ Cond.: Good _____ Fair _____ Poor _____; Need Adj./Repair: Yes _____
Interior 0 Condition: Good _____ Fair _____ Poor _____; Need Adj./Repair: Yes _____
10. Plumbing fixtures: Yes _____ No ; Good _____ Operating _____ Poor _____ Faucet Leak: Yes _____
Pressure: Normal Below Normal _____; Grouting needed at Tub/Shower Tile: Yes _____
12. Cabinets: Kitchen _____ Medicine _____ None _____
12. Stove _____ (Gas _____ Elec.); Refrigerator _____ None ; Good _____ Operating _____ Old _____
13. Fireplace: Yes _____ No ; Not Tested _____; Appears: Serviceable _____; Poor _____ Repair Damper: Yes _____

3 STAIR / 2 STAIR
COMMON TOILET ROOM
REWORK CONE SPACER 11/9/16

ROOM: FRONT HALL

1. Ceiling: Plaster _____ Sheetrock _____ Other FWS Papered _____ Painted _____
Cracked: Yes _____ No ; Evidence of Leak: NO Leak on Wall _____ Ceiling Investigate _____
2. Walls: Plaster _____ Sheetrock _____ Tile _____ Other WOOD Papered _____ Painted _____
3. Windows: No. 3; Weatherstripped: Yes 1 No 2; Cords Broken: Yes Adeq. Egress
4. Electric outlets: Number 0;
5. Floor: Wood Tile _____ Vinyl _____ Carpet _____ Condition: Good _____ Fair Poor _____; Slope: Yes
6. Trim: Wood _____ Tile _____ Steel _____ Condition: Good _____ Fair Poor _____;
7. Hardware (locks, knobs, etc.): Condition: Good _____ Serviceable Poor _____;
8. Heating Number 0; Radiators _____ Convectors _____ Grills _____ Baseboard _____ Rad. H't'g _____ Pipe Riser _____
9. Doors: Exter. 1 Weatherstripped: Yes _____ No _____ Cond.: Good _____ Fair Poor _____; Need Adj./Repair: Yes
Interior 3 Condition: Good _____ Fair Poor _____; Need Adj./Repair: Yes _____
10. Plumbing fixtures: Yes _____ No ; Good _____ Operating _____ Poor _____ Faucet Leak: Yes _____
Pressure: Normal _____ Below Normal _____; Grouting needed at Tub/Shower Tile: Yes _____
12. Cabinets: Kitchen _____ Medicine _____ None
12. Stove _____ (Gas _____ Elec.); Refrigerator _____ None ; Good _____ Operating _____ Old _____
13. Fireplace: Yes _____ No ; Not Tested _____; Appears: Serviceable _____; Poor _____ Repair Damper: Yes _____

ROOM: LADY 2 R.F. CLASS ROOM (Cellar 6)

1. Ceiling: Plaster _____ Sheetrock _____ Other FWS Papered _____ Painted _____
Cracked: Yes _____ No ; Evidence of Leak: NO Leak on Wall _____ Ceiling Investigate _____
2. Walls: Plaster _____ Sheetrock _____ Tile _____ Other _____ Papered _____ Painted _____
3. Windows: No. 10; Weatherstripped: Yes _____ No ; Cords Broken: Yes Adeq. Egress
4. Electric outlets: Number 10; same NO PLUMB FOR
5. Floor: Wood Tile _____ Vinyl _____ Carpet _____ Condition: Good _____ Fair Poor _____; Slope: Yes
6. Trim: Wood _____ Tile _____ Steel _____ Condition: Good _____ Fair Poor _____;
7. Hardware (locks, knobs, etc.): Condition: Good _____ Serviceable Poor _____;
8. Heating Number 3; Radiators _____ Convectors _____ Grills _____ Baseboard _____ Rad. H't'g _____ Pipe Riser _____
9. Doors: Exter. 0 Weatherstripped: Yes _____ No _____ Cond.: Good _____ Fair _____ Poor _____; Need Adj./Repair: Yes _____
Interior 2 Condition: Good _____ Fair Poor _____; Need Adj./Repair: Yes _____
10. Plumbing fixtures: Yes _____ No ; Good _____ Operating _____ Poor _____ Faucet Leak: Yes _____
Pressure: Normal _____ Below Normal _____; Grouting needed at Tub/Shower Tile: Yes _____
12. Cabinets: Kitchen _____ Medicine _____ None _____
12. Stove _____ (Gas _____ Elec.); Refrigerator _____ None ; Good _____ Operating _____ Old _____
13. Fireplace: Yes _____ No ; Not Tested _____; Appears: Serviceable _____; Poor _____ Repair Damper: Yes _____

FROM GIBSON'S
THE CHARACTER USING OLD PIANO
1. RADIATOR OBSERVED

ROOM-BY-ROOM INSPECTION CHECK LIST

Date: 5/25/2016

Job #: 16-36926/Town of Bridgewater

Engineer: Richard Lalancette, P.E.

Page 6 of

Water on _____ Water off _____

ROOM: Powder Room

1. Ceiling: Plaster _____ Sheetrock _____ Other Plaster Papered _____ Painted _____
Cracked: Yes No _____; Evidence of Leak: no Leak on Wall _____ Ceiling Investigate _____
2. Walls: Plaster Sheetrock _____ Tile _____ Other wood Papered _____ Painted _____
3. Windows: No. 0; Weatherstripped: Yes _____ No _____; Cords Broken: Yes _____ Adeq. Egress _____
4. Electric outlets: Number 0;
5. Floor: Wood Tile _____ Vinyl _____ Carpet _____ Condition: Good _____ Fair Poor _____; Slope: Yes
6. Trim: Wood Tile _____ Steel _____ Condition: Good _____ Fair Poor _____;
7. Hardware (locks, knobs, etc.): Condition: Good _____ Serviceable _____ Poor _____;
8. Heating Number 0; Radiators _____ Convectors _____ Grills _____ Baseboard _____ Rad. H't'g _____ Pipe Riser _____
9. Doors: Exter. 0 Weatherstripped: Yes _____ No _____ Cond.: Good _____ Fair _____ Poor _____; Need Adj./Repair: Yes _____
Interior 1 Condition: Good _____ Fair _____ Poor _____; Need Adj./Repair: Yes _____
10. Plumbing fixtures: Yes No _____; Good _____ Operating _____ Poor _____ Faucet Leak: Yes _____
Pressure: Normal Below Normal _____; Grouting needed at Tub/Shower Tile: Yes _____
12. Cabinets: Kitchen _____ Medicine _____ None _____
12. Stove _____ (Gas _____ Elec. _____); Refrigerator _____ None _____; Good _____ Operating _____ Old _____
13. Fireplace: Yes _____ No ; Not Tested _____; Appears: Serviceable _____; Poor _____ Repair Damper: Yes _____
old fireplace

ROOM: Computer Room

1. Ceiling: Plaster _____ Sheetrock Other TIN / TILES Papered _____ Painted _____
Cracked: Yes _____ No _____; Evidence of Leak: YES Leak on Wall _____ Ceiling Investigate _____
2. Walls: Plaster Sheetrock Tile _____ Other wood Papered _____ Painted _____
3. Windows: No. 0; Weatherstripped: Yes _____ No _____; Cords Broken: Yes _____ Adeq. Egress _____
4. Electric outlets: Number 4 ± : 100A;
5. Floor: Wood Tile _____ Vinyl _____ Carpet _____ Condition: Good _____ Fair Poor _____; Slope: Yes
6. Trim: Wood Tile _____ Steel _____ Condition: Good _____ Fair Poor _____;
7. Hardware (locks, knobs, etc.): Condition: Good _____ Serviceable _____ Poor _____;
8. Heating Number 1; Radiators _____ Convectors _____ Grills _____ Baseboard _____ Rad. H't'g _____ Pipe Riser _____
9. Doors: Exter. 0 Weatherstripped: Yes _____ No _____ Cond.: Good _____ Fair _____ Poor _____; Need Adj./Repair: Yes _____
Interior 2 Condition: Good _____ Fair Poor _____; Need Adj./Repair: Yes
10. Plumbing fixtures: Yes No WASH SINK OPERATING Poor _____ Faucet Leak: Yes _____
Pressure: Normal Below Normal _____; Grouting needed at Tub/Shower Tile: Yes _____
12. Cabinets: Kitchen _____ Medicine _____ None _____
12. Stove _____ (Gas _____ Elec. _____); Refrigerator _____ None _____; Good _____ Operating _____ Old _____
13. Fireplace: Yes _____ No ; Not Tested _____; Appears: Serviceable _____; Poor _____ Repair Damper: Yes _____
How to the kitchen / adjacent room
from 500000

ROOM: LP Classroom CARDS 4

1. Ceiling: Plaster _____ Sheetrock _____ Other FIBERBOARD Papered _____ Painted _____
Cracked: Yes _____ No ; Evidence of Leak: no Leak on Wall _____ Ceiling _____ Investigate _____
2. Walls: Plaster Sheetrock _____ Tile _____ Other _____ Papered _____ Painted _____
3. Windows: No. 10; Weatherstripped: Yes _____ No _____; Cords Broken: Yes Adeq. Egress
4. Electric outlets: Number 8 ± : 100A;
5. Floor: Wood Tile _____ Vinyl _____ Carpet _____ Condition: Good _____ Fair _____ Poor _____; Slope: Yes
6. Trim: Wood Tile _____ Steel _____ Condition: Good _____ Fair _____ Poor _____;
7. Hardware (locks, knobs, etc.): Condition: Good _____ Serviceable _____ Poor _____;
8. Heating Number 3; Radiators _____ Convectors _____ Grills _____ Baseboard _____ Rad. H't'g _____ Pipe Riser _____
9. Doors: Exter. 0 Weatherstripped: Yes _____ No _____ Cond.: Good _____ Fair _____ Poor _____; Need Adj./Repair: Yes _____
Interior 1 Condition: Good _____ Fair _____ Poor _____; Need Adj./Repair: Yes _____
10. Plumbing fixtures: Yes _____ No ; Good _____ Operating _____ Poor _____ Faucet Leak: Yes _____
Pressure: Normal _____ Below Normal _____; Grouting needed at Tub/Shower Tile: Yes _____
12. Cabinets: Kitchen _____ Medicine _____ None _____
12. Stove _____ (Gas _____ Elec. _____); Refrigerator _____ None _____; Good _____ Operating _____ Old _____
13. Fireplace: Yes _____ No ; Not Tested _____; Appears: Serviceable _____; Poor _____ Repair Damper: Yes _____
2 partitions disconnection
carcass from
from 500000

ROOM-BY-ROOM INSPECTION CHECK LIST

Date: 5/25/2016

Job #: 16-36926/Town of Bridgewater

Engineer: Richard Lalancette, P.E.

Page 7 of 7

Water on _____ Water off _____

ROOM: LC CLASS CRADIS / GRAD 2

1. Ceiling: Plaster _____ Sheetrock _____ Other THU Papered _____ Painted _____
Cracked: Yes No ; Evidence of Leak: YES Leak on Wall _____ Ceiling _____ Investigate _____
 2. Walls: Plaster _____ Sheetrock Tile _____ Other _____ Papered _____ Painted _____
 3. Windows: No. 5 ; Weatherstripped: Yes _____ No ; Cords Broken: Yes _____ Adeq. Egress _____
 4. Electric outlets: Number 12 ± : 106
 5. Floor: Wood Tile _____ Vinyl _____ Carpet _____ Condition: Good _____ Fair Poor _____ ; Slope: Yes
 6. Trim: Wood _____ Tile _____ Steel _____ Condition: Good _____ Fair Poor _____ ;
 7. Hardware (locks, knobs, etc.): Condition: Good _____ Serviceable _____ Poor _____ ;
 8. Heating Number 3 ; Radiators _____ Convectors _____ Grills _____ Baseboard _____ Rad. H't'g _____ Pipe Riser _____
 9. Doors: Ext. 0 Weatherstripped: Yes _____ No _____ Cond.: Good _____ Fair _____ Poor _____ ; Need Adj./Repair: Yes _____
Interior 4 Condition: Good _____ Fair Poor _____ ; Need Adj./Repair: Yes _____
 10. Plumbing fixtures: Yes _____ No ; Good _____ Operating _____ Poor _____ Faucet Leak: Yes _____
Pressure: Normal _____ Below Normal _____ ; Grouting needed at Tub/Shower Tile: Yes _____
 12. Cabinets: Kitchen _____ Medicine _____ None
 12. Stove _____ (Gas _____ Elec. _____) ; Refrigerator _____ None ; Good _____ Operating _____ Old _____
 13. Fireplace: Yes _____ No ; Not Tested _____ ; Appears: Serviceable _____ ; Poor _____ Repair Damper: Yes _____
- CONCRETE FLOOR PATIENS / DOORS ROOMS

ROOM: RC CLASS KINOSIA GARDEN

1. Ceiling: Plaster _____ Sheetrock _____ Other THU Papered _____ Painted _____
Cracked: Yes No ; Evidence of Leak: YES Leak on Wall _____ Ceiling _____ Investigate _____
 2. Walls: Plaster _____ Sheetrock Tile _____ Other _____ Papered _____ Painted _____
 3. Windows: No. 4 ; Weatherstripped: Yes _____ No ; Cords Broken: Yes _____ Adeq. Egress _____
 4. Electric outlets: Number 3 ± : PATIENS OUTLETS
 5. Floor: Wood Tile _____ Vinyl _____ Carpet _____ Condition: Good _____ Fair Poor _____ ; Slope: Yes
 6. Trim: Wood _____ Tile _____ Steel _____ Condition: Good _____ Fair Poor _____ ;
 7. Hardware (locks, knobs, etc.): Condition: Good _____ Serviceable _____ Poor _____ ;
 8. Heating Number 2 ; Radiators _____ Convectors _____ Grills _____ Baseboard _____ Rad. H't'g _____ Pipe Riser _____
 9. Doors: Ext. 0 Weatherstripped: Yes _____ No _____ Cond.: Good _____ Fair _____ Poor _____ ; Need Adj./Repair: Yes _____
Interior 2 Condition: Good _____ Fair Poor _____ ; Need Adj./Repair: Yes _____
 10. Plumbing fixtures: Yes _____ No ; Good _____ Operating _____ Poor _____ Faucet Leak: Yes _____
Pressure: Normal _____ Below Normal _____ ; Grouting needed at Tub/Shower Tile: Yes _____
 12. Cabinets: Kitchen _____ Medicine _____ None
 12. Stove _____ (Gas _____ Elec. _____) ; Refrigerator _____ None ; Good _____ Operating _____ Old _____
 13. Fireplace: Yes _____ No ; Not Tested _____ ; Appears: Serviceable _____ ; Poor _____ Repair Damper: Yes _____
- THE WALLS REPAIRS FROM ROOMS
CONCRETE FLOOR PATIENS

ROOM: POWDER ROOM

1. Ceiling: Plaster _____ Sheetrock _____ Other THU Papered _____ Painted _____
Cracked: Yes No ; Evidence of Leak: NO Leak on Wall _____ Ceiling _____ Investigate _____
 2. Walls: Plaster _____ Sheetrock Tile _____ Other _____ Papered _____ Painted _____
 3. Windows: No. 1 ; Weatherstripped: Yes _____ No ; Cords Broken: Yes Adeq. Egress _____
 4. Electric outlets: Number 2 ± : 106
 5. Floor: Wood _____ Tile _____ Vinyl THU Carpet _____ Condition: Good _____ Fair Poor _____ ; Slope: Yes
 6. Trim: Wood _____ Tile _____ Steel _____ Condition: Good _____ Fair Poor _____ ;
 7. Hardware (locks, knobs, etc.): Condition: Good _____ Serviceable _____ Poor _____ ;
 8. Heating Number 1 ; Radiators _____ Convectors _____ Grills _____ Baseboard _____ Rad. H't'g _____ Pipe Riser _____
 9. Doors: Ext. 0 Weatherstripped: Yes _____ No _____ Cond.: Good _____ Fair _____ Poor _____ ; Need Adj./Repair: Yes _____
Interior 1 Condition: Good _____ Fair Poor _____ ; Need Adj./Repair: Yes NO
 10. Plumbing fixtures: Yes No _____ ; Good _____ Operating _____ Poor _____ Faucet Leak: Yes _____
Pressure: Normal Below Normal _____ ; Grouting needed at Tub/Shower Tile: Yes _____
 12. Cabinets: Kitchen _____ Medicine _____ None
 12. Stove _____ (Gas _____ Elec. _____) ; Refrigerator _____ None ; Good _____ Operating _____ Old _____
 13. Fireplace: Yes _____ No ; Not Tested _____ ; Appears: Serviceable _____ ; Poor _____ Repair Damper: Yes _____
- CONCRETE FLOOR PATIENS

ROOM-BY-ROOM INSPECTION CHECK LIST

Date: 5/25/2016

Job #: 16-36926/Town of Bridgewater

Engineer: Richard Lalancette, P.E.

Page 8 of

Water on _____ Water off _____

ROOM: WKS ROOM CLEAN ROOM

1. Ceiling: Plaster _____ Sheetrock _____ Other Tile Papered _____ Painted _____
Cracked: Yes _____ No ; Evidence of Leak: Yes Leak on Wall _____ Ceiling Investigate _____
2. Walls: Plaster _____ Sheetrock _____ Tile _____ Other _____ Papered _____ Painted _____
3. Windows: No. 5 ; Weatherstripped: Yes _____ No TPP ; Cords Broken: Yes _____ Adeq. Egress _____
4. Electric outlets: Number 9 ; Shower
5. Floor: Wood _____ Tile _____ Vinyl Tile Carpet _____ Condition: Good _____ Fair Poor _____ ; Slope: Yes
6. Trim: Wood _____ Tile Wall Steel Wall Condition: Good _____ Fair Poor _____ ;
7. Hardware (locks, knobs, etc.): Condition: Good _____ Serviceable _____ Poor _____ ;
8. Heating Number 1 ; Radiators _____ Convectors _____ Grills _____ Baseboard _____ Rad. H't'g _____ Pipe Riser _____
9. Doors: Exter. 1 Weatherstripped: Yes _____ No _____ Cond.: Good _____ Fair _____ Poor _____ ; Need Adj./Repair: Yes _____
Interior 2 Condition: Good _____ Fair Poor _____ ; Need Adj./Repair: Yes
10. Plumbing fixtures: Yes _____ No ; Good _____ Operating _____ Poor _____ Faucet Leak: Yes _____
Pressure: Normal _____ Below Normal _____ ; Grouting needed at Tub/Shower Tile: Yes _____
12. Cabinets: Kitchen _____ Medicine _____ None
12. Stove _____ (Gas _____ Elec. _____) ; Refrigerator _____ None ; Good _____ Operating _____ Old _____
13. Fireplace: Yes _____ No ; Not Tested _____ ; Appears: Serviceable _____ ; Poor _____ Repair Damper: Yes _____

CONVERT THIS ROOM TO BOARD OVER RUMOR
PLASTER WITH CERAMIC

ROOM: ROOM CONSTRUCTION

1. Ceiling: Plaster _____ Sheetrock _____ Other Tile Papered _____ Painted _____
Cracked: Yes _____ No ; Evidence of Leak: NO Leak on Wall _____ Ceiling _____ Investigate _____
2. Walls: Plaster _____ Sheetrock _____ Tile _____ Other _____ Papered _____ Painted _____
3. Windows: No. 1 ; Weatherstripped: Yes _____ No _____ ; Cords Broken: Yes Adeq. Egress _____
4. Electric outlets: Number 6 ; Shower
5. Floor: Wood _____ Tile _____ Vinyl Tile Carpet _____ Condition: Good _____ Fair Poor _____ ; Slope: Yes
6. Trim: Wood _____ Tile Wall Steel _____ Condition: Good _____ Fair Poor _____ ;
7. Hardware (locks, knobs, etc.): Condition: Good _____ Serviceable _____ Poor _____ ;
8. Heating Number 1 ; Radiators _____ Convectors _____ Grills _____ Baseboard _____ Rad. H't'g _____ Pipe Riser _____
9. Doors: Exter. 0 Weatherstripped: Yes _____ No _____ Cond.: Good _____ Fair _____ Poor _____ ; Need Adj. Repair: Yes _____
Interior 1 Condition: Good _____ Fair _____ Poor _____ ; Need Adj./Repair: Yes _____
10. Plumbing fixtures: Yes _____ No ; Good _____ Operating _____ Poor _____ Faucet Leak: Yes _____
Pressure: Normal _____ Below Normal _____ ; Grouting needed at Tub/Shower Tile: Yes _____
12. Cabinets: Kitchen _____ Medicine _____ None
12. Stove _____ (Gas _____ Elec. _____) ; Refrigerator _____ None ; Good _____ Operating _____ Old _____
13. Fireplace: Yes _____ No ; Not Tested _____ ; Appears: Serviceable _____ ; Poor _____ Repair Damper: Yes _____

CONVERT THIS ROOM TO BOARD OVER RUMOR
PLASTER WITH CERAMIC

ROOM: 2 RECEPTION

1. Ceiling: Plaster _____ Sheetrock _____ Other Tile Papered _____ Painted _____
Cracked: Yes _____ No ; Evidence of Leak: YES Leak on Wall _____ Ceiling Investigate _____
2. Walls: Plaster _____ Sheetrock _____ Tile _____ Other _____ Papered _____ Painted _____
3. Windows: No. 5 ; Weatherstripped: Yes _____ No _____ ; Cords Broken: Yes Adeq. Egress _____
4. Electric outlets: Number 13 ; Shower
5. Floor: Wood _____ Tile _____ Vinyl Tile Carpet _____ Condition: Good _____ Fair Poor _____ ; Slope: Yes _____
6. Trim: Wood _____ Tile Wall Steel _____ Condition: Good _____ Fair Poor _____ ;
7. Hardware (locks, knobs, etc.): Condition: Good _____ Serviceable _____ Poor _____ ;
8. Heating Number 2 ; Radiators _____ Convectors _____ Grills _____ Baseboard _____ Rad. H't'g _____ Pipe Riser _____
9. Doors: Exter. 0 Weatherstripped: Yes _____ No _____ Cond.: Good _____ Fair _____ Poor _____ ; Need Adj./Repair: Yes _____
Interior 2 Condition: Good _____ Fair Poor _____ ; Need Adj./Repair: Yes _____
10. Plumbing fixtures: Yes _____ No ; Good _____ Operating _____ Poor _____ Faucet Leak: Yes _____
Pressure: Normal _____ Below Normal _____ ; Grouting needed at Tub/Shower Tile: Yes _____
12. Cabinets: Kitchen _____ Medicine _____ None
12. Stove _____ (Gas _____ Elec. _____) ; Refrigerator _____ None ; Good _____ Operating _____ Old _____
13. Fireplace: Yes _____ No ; Not Tested _____ ; Appears: Serviceable _____ ; Poor _____ Repair Damper: Yes _____

BOARD OVER RUMOR SUBMIT BY E. LABREY

ROOM-BY-ROOM INSPECTION CHECK LIST

Date: 5/25/2016

Job #: 16-36926/Town of Bridgewater

Engineer: Richard Lalancette, P.E.

Page 9 of

Water on _____ Water off _____

ROOM: BRUNNERY / STAIR

1. Ceiling: Plaster _____ Sheetrock Other TWO Papered _____ Painted _____
Cracked: Yes _____ No ; Evidence of Leak: YES Leak on Wall _____ Ceiling Investigate
 2. Walls: Plaster _____ Sheetrock Tile _____ Other _____ Papered _____ Painted _____
 3. Windows: No. 2 ; Weatherstripped: Yes No _____ ; Cords Broken: YES Adeq. Egress _____
 4. Electric outlets: Number 3 E.
 5. Floor: Wood _____ Tile _____ Vinyl TWO Carpet _____ Condition: Good _____ Fair _____ Poor _____ ; Slope: Yes _____
 6. Trim: Wood _____ Tile Steel _____ Condition: Good Fair Poor _____ ;
 7. Hardware (locks, knobs, etc.): Condition: Good _____ Serviceable Poor _____ ;
 8. Heating Number 1 ; Radiators _____ Convectors _____ Grills _____ Baseboard Rad. H't'g _____ Pipe Riser _____
 9. Doors: Exter. 1 Weatherstripped: Yes No _____ Cond.: Good _____ Fair _____ Poor _____ ; Need Adj./Repair: Yes _____
Interior 3 Condition: Good _____ Fair _____ Poor _____ ; Need Adj./Repair: Yes _____
 10. Plumbing fixtures: Yes _____ No NO WATER Operating _____ Poor _____ Faucet Leak: Yes _____
Pressure: Normal Below Normal _____ ; Grouting needed at Tub/Shower Tile: Yes _____
 12. Cabinets: Kitchen _____ Medicine _____ None
 12. Stove _____ (Gas _____ Elec. _____) ; Refrigerator _____ None ; Good _____ Operating _____ Old _____
 13. Fireplace: Yes _____ No _____ ; Not Tested _____ ; Appears: Serviceable _____ ; Poor _____ Repair Damper: Yes _____
- CRACKED IN FLOOR UNDER WALL REPAIR BRUNNERY STAIR
CRACKED IN STAIR REPAIR
BASEBOARD WALL REPAIR
DOOR WEATHERSTRIP - P
ALARM PANEL
TISP TIPS NOICE

ROOM:

1. Ceiling: Plaster _____ Sheetrock _____ Other _____ Papered _____ Painted _____
Cracked: Yes _____ No _____ ; Evidence of Leak: _____ Leak on Wall _____ Ceiling _____ Investigate _____
2. Walls: Plaster _____ Sheetrock _____ Tile _____ Other _____ Papered _____ Painted _____
3. Windows: No. _____ ; Weatherstripped: Yes _____ No _____ ; Cords Broken: Yes _____ Adeq. Egress _____
4. Electric outlets: Number _____ ;
5. Floor: Wood _____ Tile _____ Vinyl _____ Carpet _____ Condition: Good _____ Fair _____ Poor _____ ; Slope: Yes _____
6. Trim: Wood _____ Tile _____ Steel _____ Condition: Good _____ Fair _____ Poor _____ ;
7. Hardware (locks, knobs, etc.): Condition: Good _____ Serviceable _____ Poor _____ ;
8. Heating Number _____ ; Radiators _____ Convectors _____ Grills _____ Baseboard _____ Rad. H't'g _____ Pipe Riser _____
9. Doors: Exter. _____ Weatherstripped: Yes _____ No _____ Cond.: Good _____ Fair _____ Poor _____ ; Need Adj./Repair: Yes _____
Interior _____ Condition: Good _____ Fair _____ Poor _____ ; Need Adj./Repair: Yes _____
10. Plumbing fixtures: Yes _____ No _____ ; Good _____ Operating _____ Poor _____ Faucet Leak: Yes _____
Pressure: Normal _____ Below Normal _____ ; Grouting needed at Tub/Shower Tile: Yes _____
12. Cabinets: Kitchen _____ Medicine _____ None _____
12. Stove _____ (Gas _____ Elec. _____) ; Refrigerator _____ None _____ ; Good _____ Operating _____ Old _____
13. Fireplace: Yes _____ No _____ ; Not Tested _____ ; Appears: Serviceable _____ ; Poor _____ Repair Damper: Yes _____

ROOM:

1. Ceiling: Plaster _____ Sheetrock _____ Other _____ Papered _____ Painted _____
Cracked: Yes _____ No _____ ; Evidence of Leak: _____ Leak on Wall _____ Ceiling _____ Investigate _____
2. Walls: Plaster _____ Sheetrock _____ Tile _____ Other _____ Papered _____ Painted _____
3. Windows: No. _____ ; Weatherstripped: Yes _____ No _____ ; Cords Broken: Yes _____ Adeq. Egress _____
4. Electric outlets: Number _____ ;
5. Floor: Wood _____ Tile _____ Vinyl _____ Carpet _____ Condition: Good _____ Fair _____ Poor _____ ; Slope: Yes _____
6. Trim: Wood _____ Tile _____ Steel _____ Condition: Good _____ Fair _____ Poor _____ ;
7. Hardware (locks, knobs, etc.): Condition: Good _____ Serviceable _____ Poor _____ ;
8. Heating Number _____ ; Radiators _____ Convectors _____ Grills _____ Baseboard _____ Rad. H't'g _____ Pipe Riser _____
9. Doors: Exter. _____ Weatherstripped: Yes _____ No _____ Cond.: Good _____ Fair _____ Poor _____ ; Need Adj./Repair: Yes _____
Interior _____ Condition: Good _____ Fair _____ Poor _____ ; Need Adj./Repair: Yes _____
10. Plumbing fixtures: Yes _____ No _____ ; Good _____ Operating _____ Poor _____ Faucet Leak: Yes _____
Pressure: Normal _____ Below Normal _____ ; Grouting needed at Tub/Shower Tile: Yes _____
12. Cabinets: Kitchen _____ Medicine _____ None _____
12. Stove _____ (Gas _____ Elec. _____) ; Refrigerator _____ None _____ ; Good _____ Operating _____ Old _____
13. Fireplace: Yes _____ No _____ ; Not Tested _____ ; Appears: Serviceable _____ ; Poor _____ Repair Damper: Yes _____

SUPPLEMENTAL INSPECTION CHECK LIST

Date: 5/25/2016

Job #: 16-36926/Town of Bridgewater

Engineer: Richard Lalancette, P.E.

Page 10 of 10

- 1. Overall, maintenance has been: Good _____ Fair Poor _____
- 2. Overall, current condition is: Above Average _____ Average Below Average
- 3. Access:
 - 3.1 Inaccessible crawl spaces: Yes _____ No Partial _____
 - 3.2 Inaccessible attic spaces: Yes No _____ Partial _____
 - 3.3 Evidence of rot or other problems in inaccessible areas?
Yes _____ No Uncertain _____
 - 3.4 Recommend further investigation: Yes _____ No
- 4. Structure:
 - 4.1 Some structural repairs are required soon: Yes No _____
Describe: TRUSS WORK
 - 4.2 Number of outdoor decks: 0 Condition: Good _____ Fair _____ Poor _____
 - 4.3 Number of porches: 1 Condition: Good _____ Fair _____ Poor _____
 - 4.4 General quality of structure: Good _____ Fair Poor _____
- 5. Electric:
 - 5.1 Where visible, wiring consists of BX Romex Knob and Tube _____ Fabric _____
 - 5.2 General condition of wiring: Good Fair _____ Poor _____
 - 5.3 Outdoor/underground wiring: Yes _____ No evidence
 - 5.4 Entrance panel: Old _____ New Good Fair _____ Poor _____
- 6. Security:
 - 6.1 Alarm system: Yes No FIRE Not visible _____
 - 6.2 Locks on windows: Yes No _____ Partial _____
 - 6.3 Door locking hardware: Good _____ Fair Poor _____
 - 6.4 Smoke alarms: Yes W/ FMO Operating: Yes _____ No _____ Not all _____
 - 6.5 Carbon monoxide detectors: Yes _____ No Operating: Yes _____ No _____ Not all _____
 - 6.6 Hand rails on stairs: Yes No _____ Not all _____
- 7. Chimneys:
 - 7.1 Number: 1 Type: Block _____ Brick Other _____
 - 7.2 Use: Oil Gas _____ Wood _____ Coal _____
 - 7.3 Multiple use of single chimney: No _____ Yes Not visible _____
 - 7.4 Multi-flue chimney: Yes _____ No No. of flues _____
 - 7.5 General condition: Good Fair _____ Poor _____
 - 7.6 Chimneys lined: All _____ None _____ Partial _____ Not visible
 - 7.7 Chimney caps: Yes _____ No
- 8. Hazardous materials:
 - 8.1 Evidence of asbestos insulation: Yes _____ No Not visible _____
Condition: Good _____ Fair _____ Poor _____
 - 8.2 Evidence of UFFI: Yes _____ No Not visible _____
- 9. General:
 - 9.1 Garage: Serviceable NA Poor _____; Fire Separation in Garage: Yes _____ No _____; Step Down: Yes _____ No _____
 - 9.2 Electric garage door opener: Yes NA No _____ Operating: Yes _____ No _____ Safety cables: Yes _____ No _____
 - 9.3 Underground oil tank: Yes _____ Not evident
 - 9.4 Distance between well and septic system: Adequate NA Substandard _____ Not visible _____
- 10. Additional investigative work recommended:
 - 10.1 Pump out and evaluate septic tank: Yes NA
 - 10.2 Test air quality: Yes Radon & Carbon
 - 10.3 Radon Mitigation System: Y _____ N Termination _____ Marked _____ Pressure Gage _____ Fan Location _____
 - 10.4 Investigate inaccessible areas: Yes NA
- 12. Energy Code Certification: Required: Yes _____ No ; Provided: Yes _____ No
- 12. Other comments:
 - SCAVENGE ROOF LINE WORKS AT FOOT
 - CHIMNEY WORK @ REAR
 - SOFFIT WATER ROT
 - ROT IN TRUCK DR. INSULATION
 - DAMAGED LB. INSULATION
 - N/S ROOF LB. SOFFIT ON
 - ROT IN PLATE SOFFIT FASCIA
 - ROT IN SOFFIT TRIM TRIM
 - ROT IN CORNER TRIM
 - N/S ROOF AIR ENTRY FROM
 - SPRAY FOAM UNDER ROOF TRIM
 - SS ROOF FASCIA MOVED @ REAR
 - VALVES

LALANCETTE ENGINEERS

PO BOX 6348
 RUTLAND, VT 05702-6348
 TEL 802-747-4535
 FAX 802-775-2307
 info@criterion-lalancette.com

AGREEMENT FOR SERVICES - Building Inspection

This is the complete agreement regarding engineering services to be provided by Criterium-Lalancette Engineers (ENGINEER) related to the property described below. This is intended to be a legally binding agreement. Please read it carefully.

Client(s) Full Name(s):	Town of Bridgewater Attn: Town Select Board & Ms. Nancy Robinson 7335 US Route 4 Bridgewater, VT 05034	Property:	Bridgewater Village School 7313 US Route 4 Bridgewater, VT 05034 Job #36926
Schedule: Day: Wednesday Date: 5/25/2016 (extreme weather permitting) Time: 8:30 a.m. (approximate)			
Description of Property:			
Approximate age or year built?	1913 w/Reno	Property type?	Commercial
Approximate size? (sq. footage)	12,952	Additional buildings?	1 Bldg
Inspection services to be provided:		Testing services to be provided:	
X	Standard Inspection	T.B.D.	TS04.1 Standard Water Test (\$165.00)
	Standard Inspection – Other		TS11 Radon Water Test (\$65.00)
	Exhaustive Inspection		TS14 Gross Alpha Water Test (\$145.00)
X	TS09 Radon Air Test (\$145.00)	\$145.00	TS15 Uranium Water Test (\$75.00)


Fee is \$150.00 per hour time on-site and report writing (min. \$500.00) + testing fee(s). A deposit of \$1,645.00 is due at or before the inspection (unless paying by credit card). Any balance will be refunded/invoiced with written report. Estimates could change if physical property information provided to our office varies from that provided above (i.e.: building type, other buildings to be inspected, square footage, etc.). 48-hour notice of cancellation is requested. Otherwise, a cancellation fee of \$150.00 plus fees for advance testing services administered prior to the inspection date will be charged to your credit card.


All inspections are performed in accordance with the Standards of Practice and Code of Ethics of The American Society of Home Inspectors (ASHI), a copy of which is available on request or at www.ashi.org and in a manner consistent with that level of care and skill that is ordinarily exercised by members of the profession practicing under similar conditions at the time the services are performed. While we will report readily visible evidence of mold infestations, this inspection should not be considered a specific mold investigation of any kind.

The results of the inspection will be provided in a written report prepared exclusively for your benefit. Reports are typically available 2-3 business days following the inspection, unless prior arrangements are made. If two trips need to be made to the property, testing may be started early. However, some test results may take longer.

You are encouraged to be at the inspection to discuss your questions and concerns. However, **the written report is the exclusive source of information regarding our observations and conclusions.** All discussions that occur at the inspection are preliminary in nature and should not be the basis for any final decisions regarding this property. Further, owning any property involves some risk. No inspection can reveal everything that might be of interest or significance to you regarding this property.


Our inspection is not a guarantee or warranty regarding the condition of this building. Except as otherwise noted herein, our maximum liability for loss suffered by the CLIENT due to any cause is limited to our inspection fee. If you bring an action against the ENGINEER and the ENGINEER prevails, ENGINEER shall be entitled to recover costs and expenses, including reasonable attorneys' fees and costs.


 Client Initial or "X"


 Engineer Initial



LICENSED
 PROFESSIONAL
 ENGINEERS

BUILDING INSPECTIONS
 ANALYSIS & DIAGNOSTICS
 RESERVE STUDIES
 CAPITAL NEEDS ASSESSMENTS
 ENVIRONMENTAL TESTING



AGREEMENT FOR SERVICES (continued)
Building Inspection

CHOICE OF INSPECTION SERVICES: After reviewing these descriptions, both the client and engineer should initial where noted, to indicate the type of inspection chosen. As our client, you are making a choice of services to be provided. If you have any questions, please contact us immediately.

 _____ Client Initial or "X"  _____ Engineer Initial	<p>STANDARD INSPECTION: A limited visual inspection to identify significant deficiencies and/or repairs needed in the major systems (structural, heating, air conditioning, plumbing, electrical, roof, exterior) as well as provide a general understanding of the property. This is a limited inspection based on visible evidence readily available during the inspection (without moving furnishings, removing finishes, etc.) and is the opinion of the engineer performing the inspection.</p>
---	---


_____ Client Initial or "X" _____ Engineer Initial	<p>EXHAUSTIVE INSPECTION: A STANDARD INSPECTION PLUS invasive testing and/or equipment disassembly as approved by client and property owner, in advance, to gather all reasonably available and relevant information about the property. This inspection is specifically not limited to readily available visible evidence and requires invasive testing which may include moving furnishings, removing wall coverings and/or drilling into wall cavities (to check for structural damage, for example) and requires the current owner's written permission. Unlike the Standard or Limited Inspection, our maximum liability for loss suffered by the CLIENT due to any cause is limited to our inspection fee or \$10,000.00, whichever is greater. In addition, because of the additional services provided under an Exhaustive Inspection, the results of the inspection will be provided in a written report, typically available within 5 business days after the inspection unless prior arrangements are made.</p>
---	---


CHOOSE ONE OF THESE (A.), (B.), OR (C.) REPORT FORMAT OPTIONS: (PLEASE INITIAL or "X" WHICH INSPECTION REPORT FORMAT YOU WISH TO RECEIVE (GENERALLY WITHIN 2-3 BUSINESS DAYS) AFTER THE BUILDING INSPECTION).

 _____ Client Initial or "X"	(A.) Electronic Copy via Email (<i>only</i>) to the following e-mail address (I understand that I may request a hard copy at any time in the future for no additional charge). <u>townbridg@comcast.net</u>
_____ Client Initial or "X"	(B.) Printed Copy (<i>only</i>)
_____ Client Initial or "X"	(C.) Electronic & Printed Hard Copy (<i>both</i>)

MOLD EXCLUSION: This inspection is not for the specific purpose of determining the presence of organic substances in the building. If, however, during the inspection, we knowingly encounter such substances, we will notify you of the presence of these substances without accepting any liability whatsoever for any damage or harm caused by the substances. It is your responsibility to determine if further testing is required and to retain an independent, qualified professional to perform such tests.

The above is understood and accepted.



 Authorizing Signature


 Engineer Signature

 5/17/16
 (Date)

 5/21/16
 (Date)

Professional Qualifications and Experience

Richard L. Lalancette, P.E.

Area of Expertise

Richard Lalancette is a licensed, Professional Engineer in Vermont specializing in building technology and construction. His knowledge of construction is extensive as he has been employed in positions ranging from pipefitter to project manager on a wide variety of construction projects. In addition, Richard worked as the maintenance superintendent of a large Vermont manufacturing firm and as such was responsible for preventative and repair maintenance of all facilities.

In 1988, he founded Criterium-Lalancette Engineers. Criterium-Lalancette Engineers is one of 70 offices of Criterium Engineers, the largest engineering group in the nation specializing in pre-purchase home and building inspections, having inspected more than 750,000 structures.

Richard has conducted over 6,500 inspections personally, and has overseen the work of over 20,000 inspections conducted by licensed, Professional Engineers working for the firm. Richard has also taught many seminars and given numerous talks to real estate agents, attorneys, bankers, and first-time home buyers over the past 20 years.

Qualifications

Before owning and operating his own engineering consulting firm, Richard was employed by Omya, Inc. of Florence, Vermont as Maintenance Superintendent. He was responsible for a \$2 million maintenance effort including both physical plant and process equipment. In addition to the direct supervision of a 15 member maintenance staff, he also performed engineering as required to support this effort.

Prior to this assignment, Richard worked for Elling Brothers Mechanical Contractors of Somerville, New Jersey, where he had total responsibility for construction projects ranging from a small cogeneration facility to major plant expansions for Fortune 500 companies.

Richard began his career with Pizzagalli Construction Company of South Burlington, Vermont. His duties with Pizzagalli ranged from estimating and scheduling, to the management of several large projects in the Virgin Islands.

Education & Memberships

Richard is a licensed, Professional Engineer in Vermont, Board Certified by the Building Inspection Engineers Certification Institute (BIECI), a Certified American Society of Home Inspectors (ASHI) Inspector, and an approved HUD Fee Inspector. He is also a licensed Vermont Property Inspector and a licensed New Hampshire Home Inspector. He holds memberships in the National Academy of Building Inspection Engineers (NABIE), the National Society of Professional Engineers (NSPE), and Community Associations Institute (CAI). Richard is also a member of the Rutland South Rotary Club (Club President, 2007-2008).

Richard holds a Bachelor of Science degree in Mechanical Engineering, with honors, from the University of Vermont.

CRITERIUM[®] LALANCETTE ENGINEERS

PO BOX 6348
RUTLAND, VT 05702-6348
TEL 802-747-4535
800-639-4535
FAX 802-775-2307
info@criterium-lalancette.com

Pre-Title Check List

The attached report is intended to focus on the major engineering systems (structure, heating and cooling, plumbing and electric) in the building you are considering. While spot checks of many components (such as switches, outlets, fixtures, etc.) were made during the inspection and any significant deficiencies noted in this report, it's important to understand that the condition of these components can change at any time. Therefore, we highly recommend at least one more visit be made to these premises before taking title. This checklist is offered as a guide for that final visit.

Allow sufficient time to comfortably complete the list. Please note that not all of these items will apply to every building.

- | | |
|---|--|
| <input type="checkbox"/> Dishwasher | <input type="checkbox"/> Electrical outlets |
| <input type="checkbox"/> Garbage disposal | <input type="checkbox"/> Light fixtures |
| <input type="checkbox"/> Stove | <input type="checkbox"/> Fireplace/Stove |
| <input type="checkbox"/> Refrigerator | <input type="checkbox"/> Leaks (wall, ceiling) |
| <input type="checkbox"/> Clothes washer | <input type="checkbox"/> Broken glass |
| <input type="checkbox"/> Clothes dryer | <input type="checkbox"/> All window screens |
| <input type="checkbox"/> Water pump | <input type="checkbox"/> Window locks |
| <input type="checkbox"/> Water heater | <input type="checkbox"/> Door locks and latches |
| <input type="checkbox"/> Sump pump | <input type="checkbox"/> All keys available |
| <input type="checkbox"/> Heating system | <input type="checkbox"/> Alarm/Security systems |
| <input type="checkbox"/> Electric heaters | <input type="checkbox"/> Garage door opener(s) |
| <input type="checkbox"/> Air conditioning | <input type="checkbox"/> Swimming pool equipment |
| <input type="checkbox"/> Central vacuum system | <input type="checkbox"/> Lawn sprinkler |
| <input type="checkbox"/> Plumbing fixtures | <input type="checkbox"/> Sidewalks |
| <input type="checkbox"/> Whirlpools/Spas/Saunas | <input type="checkbox"/> Driveways |
| <input type="checkbox"/> Tile work in bath | <input type="checkbox"/> Septic/waste system |


Often weeks and months pass between our initial inspection and your closing on the property. Your involvement in making this final inspection will help assure you of the home you deserve.

Copyright 1992, **CRITERIUM ENGINEERS**

**LICENSED
PROFESSIONAL
ENGINEERS**

BUILDING INSPECTIONS
ANALYSIS & DIAGNOSTICS
RESERVE STUDIES
CAPITAL NEEDS ASSESSMENTS
ENVIRONMENTAL TESTING

Visit our web site:
www.criterium-lalancette.com



CRITERIUM[®] LALANCETTE ENGINEERS

PO BOX 6348
RUTLAND, VT 05702-6348
TEL 802-747-4535
800-639-4535
FAX 802-775-2307
info@criterium-lalancette.com

Glossary

Alligatoring: Square-patterned grain cracking of paint surface often caused by too many layers.

Amperage: An ampere is a measure of the "volume" of electrical current available. The more amperage available, the more electrical devices can be connected to the system.

Anchor Bolt: L-shaped bolt with threaded end that connects the wooden sill to the top of the foundation wall.

Armored Cable: Commonly called BX; a moderately flexible metal sheathed cable.

Artesian Well: A well which penetrates a confined subsurface water source which is under sufficient pressure to cause the water to rise in the well casing itself.

Backfill: Loose fill graded against masonry walls in an open excavation, covered with topsoil.

Back Flow Prevention Device: On hot water steam boiler a one way flow valve. Also, called a non-return valve. It also keeps the water from the boiler from getting in to the drinking water.

Bearing Wall: Walls that transfer structural loads from building components above them.

Bleeding: 1) Removing trapped air from radiators, convectors, or 2) the appearance of discoloration or stains under a finished, surface coat.

Blistering: Bubbles in paint. These are often caused by excessive moisture working through the wall from the inside.

Block: Generally, any masonry unit larger than a brick; usually set in mortar as in a block wall.

Boiler: A heating unit in which hot water or steam is produced.

Bollard: Short vertical posts. In the lighting industry, the term is used to describe short, post-like lighting fixture.

Bowed: Unsatisfactory timber (specifically framing members) that has been stored or dried unevenly, resulting in a natural curve along its length.

Bridging: Stiffeners fitted between floor joists; common bridging is an X-pattern, solid bridging is a short length of same-size floor joist timber.

BTU: British Thermal Unit—a heat measurement.

Building Paper: Thick, pinkish paper used between plywood subfloor and finished flooring.

Built-Up Roofing: Layers of asphalt-based roofing overlapped, sealed and bonded with hot tar; applied to flat roof decks.

BX: Common term for semiflexible, metal-encased electrical wiring.

Cesspool: A subsurface waste water disposal chamber with no attached drainage field (leach

bed).

Checking: A short, narrow crack along the grain of structural timbers. Different from a split that goes through the full thickness of the wood.

Check Valve: Fitting that prevents the reverse flow of water in piping; commonly used on sump pump installations or floor drains.

Chlordane: Poisonous chemical used for eradicating termites.

Circuit Breaker: Switches mounted in the main electrical panel that trip automatically to prevent overloading the circuit.

Circulator: Pump and motor mounted on hot water furnace that pushes heated water through the piping system.

Clear Lumber: The highest grades of lumber; free from visible defects and knots.

Clerestory: The upper portion of a wall containing windows for supplying natural light to the building.

Closed Valley: Pattern of overlapping, interlaced shingles across the intersection of two sloping roofs. An open valley uses metal flashing.

Combustion Efficiency: A measure of the amount of fuel burned that actually produces heat. For example, 75% combustion efficiency means 75% of the fuel burned is producing heat.

Compactness: As it relates to energy efficiency and interior traffic flow, compactness suggests the maximum amount of interior space for the minimum amount of exterior wall area. A sphere (while impractical) would represent the most compact shape and floor plan a home could have.

Compressor: Mechanical heart of a cooling system that forces refrigerant through the system.

Counter flashing: A metal strip that covers the top edge of conventional flashing (frequently used around chimneys); allows for expansion and contraction between different building materials without breaking the flashing seal against the weather.

Course: One row of shingles, bricks or masonry block placed horizontally.

Crawl Space: Area between the floor joists and the ground surrounded by the foundation wall.

Creosote: Liquid chemical applied to raw timber that protects it from the weather.

Cricket: Metal flashing placed on the "up-roof" side of the chimney to deflect roof water to either side of the chimney.

Deflection: Downward force on rafters, joists and girders, causing the center of the timber to bow downward over the center of the span.

Drip Bead: Common form of capillary break

groove cut under window sills.

Drip Edge: Lengths of L-shaped metal flashing placed along the edges of a roof to seal the space between the shingles and the roof deck from the weather.

Dry Rot: Timber decay characterized by sponginess and crumbling; caused by dampness and spread by a bacteria.

Drywall: Common form for paper-finished gypsum wallboard; also called sheetrock.

Dry Well: Rock-filled hole in the ground to collect and distribute roof water or excessive ground water.

Dug Well: A dug well is usually not more than ten or twenty feet deep and penetrates a subsurface water source (ground water) close to the surface.

Eaves: The overhanging section of a sloping roof.

Efflorescence: White powder residue on concrete masonry, usually indicates moisture migration through concrete.

Fascia: A wide vertical board running horizontally across the ends of the rafters.

Felt Paper: Common term for asphalt-impregnated building paper applied between wood roof decking and shingles.

Flashing: Metal stripping to seal seams between sections of roofing or between roofing and other materials or metal caps sealing the joint between upper door and window frames and exterior siding.

Floor Zones: Areas of a floor plan that can be distinguished by their function. For example, garage, workshop, hobby area, kitchen, family area, etc.

Footing: Enlargement at the base of a foundation wall to support and distribute the load.

Forced Air: An air conditioning or heating system that relies on a motor-driven fan for distribution.

Foundation: Lower part of the building that supports the superstructure.

Frame: The skeleton of a home including the major framing members such as rafters, studs and joists.

Furnace: A heating unit in which hot air is produced.


Gable: Triangular section of the end wall of a building with a sloping roof.

G.F.C.I. (or G.F.L.): Ground Fault Circuit Interrupter, a quick-tripping circuit breaker that can cut off power 25 milliseconds after detecting current leakage. NOTE-The National Electrical

LICENSED
PROFESSIONAL
ENGINEERS

BUILDING INSPECTIONS
ANALYSIS & DIAGNOSTICS
RESERVE STUDIES
CAPITAL NEEDS ASSESSMENTS
ENVIRONMENTAL TESTING

Visit our web site:
www.criterium-lalancette.com



Code now requires these circuit breakers in all newly built bathrooms, exterior outlets and kitchens.

Ghosting: Darkening and discoloration of wallboard nailheads and compound-filled wallboard joints caused by unequal temperature and moisture transmission through the wall.

Girder: Timber (sometimes a steel I-beam) that supports beams and floor joists.

Gravity Distributed: In heating systems, hot water and hot air are sometimes distributed by the natural thermal currents within the air or water. This is referred to as gravity distribution.

Ground Wire: Electrical wire that protects against shock hazards by transferring leaking or abnormal current back through the grounding system into the earth.

Hard Water: Water with a high mineral content.

Header: Timber across an opening in the framing system that supports framing members interrupted by the opening.

Heat Pump: A year-round heating and cooling plant best suited to moderate climates; technically a compressor-driven, refrigerant cooling system that functions as a heater when the cooling cycle is reversed.

Heaving: Upward pressure of earth caused by frost action.

Insulation: Any material which effectively restricts the flow of heat (thermal transmission) through it. Fiberglass, cellulose, styrofoam, etc. are common examples.

Jack Stud: Part-height support stud placed beneath the ends of a header across an opening, nailed to a full-length stud that extends above the header.

Joist: Wood or steel framing member directly supporting a floor or ceiling.

K.D.: Short for kiln-dried, signifying lumber with extreme dimensional stability due to low moisture content.

Leaching Field: Elongated, buried piping or chamber system placed beyond the septic tank in a waste disposal system which gradually filters liquid wastes into the earth.

Leader: Vertical pipe running between the gutter and the ground or an underground piping system.

Ledger: Timber nailed flush with the bottom of a beam or joist, used to support a timber butting at right angles.

Light: Individual panel of glass; describing the design of a double-hung window as in 8 over 8 lights.

Lignin: Organic substance which acts as binder for cellulose fibers in wood and adds strength and stiffness to cell walls.

Lintel: Structural member across the top of an opening; commonly a stone or masonry equivalent to a wood frame header.

Loop: Self-contained circuit of a hot water heating system.

Nosing: Rounded extension of a stair tread that projects beyond the vertical riser.

PVC: Polyvinylchloride—a type of "plastic" pipe used commonly for drain lines and less commonly for water distribution lines.

Perimeter Drain: A common reference for a system of drain pipes located at the base of the foundation wall to collect and carry water away from a basement space.

Permeability: A measure of the ability for vapor (moisture, air, etc.) to pass through a substance. For example, a window pane is less permeable than a screen.

Pier: Masonry load-bearing support independent of the main foundation.

Pitch: Commonly the angle of a sloping roof; the ratio of height to the span (as in 4 on 12).

Plate: Single or double layer of 2 x 4 or 2 x 6 along the top of a stud wall.

Plenum: Enclosed air chamber.

Plumb: Perfectly vertical; at right angles to a perfectly level line.

Pointing: Cleaning loose mortar from joints between masonry (also called raking the joints) and refilling with fresh mortar.

Post Foundation: A system of posts (most commonly concrete or wood) set into the ground at regular intervals to support the frame of a home above it.

Pressure-Treated: Wood timbers treated with chemical preservatives under enough pressure to force the treatment deeply into the wood. The purpose is to prevent deterioration.

Rafters: Sloping timbers extending from the eaves to the roof ridge.

Recovery Rate: The rate at which a water heater will recover from the use of hot water by producing more.

R Factor: Measurement of a material's resistance to heat transmission; displayed on insulation; higher numbers give more insulating protection.

Ridge: The horizontal line along the highest part of the roof.

Rip Edge: Lengths of L-shaped metal flashing placed along the edges of a roof to seal the space between the shingles and the roof deck from the weather.

Riser: Vertical board set between stair treads.

Roll Roofing: Continuous strips of asphalt roofing applied with an overlap along the horizontal seam, particularly on low roofs.

Romex: Plastic-sheathed, flexible wire cable.

Sash: Framework that supports glass in a window.

Septic Tank: A subsurface tank (most commonly of concrete) which allows solids to settle out of waste water before the water flows to a drainage bed or leaching field.

Service Entrance: The point where the utility company's line enters the main electrical fuse or breaker box.

Sheathing: Primary covering over framing.

Shim: Small piece of material used to support adjustments in materials to achieve level or plumb surfaces.

Slab-On-Grade: A concrete floor slab placed directly on the ground.

Sleepers: Timbers usually laid flat, resting on the ground or concrete slab to support flooring.

Slope: A steep or gradual change (up or down) in the ground level.

Soffit: Surface under roof eaves overhanging an exterior wall.

Stud: Vertical, structural timber used to frame a wall.

Subfloor: Structural flooring laid directly over the floor joists; covered by finished flooring or underlayment.

Sump: A chamber (most typically a hole in the basement floor) into which water (from perimeter drain, etc.) can flow from which it is discharged either by a sump pump or a gravity drain.

Swale: Shallow depression to collect and transfer water. A type of surface drainage.

Taping: Process of applying joint compound, perforated tape and successive coats of joint compound to conceal the seams between gypsum wallboard panels.

Termite Shield: Metal strip fastened over the top of the foundation and angled a short distance down each side or a barrier to separate masonry and wood components of the structure.

Toenailing: Practice of driving nails at an angle through the sides of a stud or other timber near the end where it butts another timber.

To The Weather: Describes the portion of a material, usually siding, exposed to the elements.

Trap: U- or S-shaped pipe fitted beneath fixtures so that a water seal prevents septic odor from entering the house.

Tread: Flat, horizontal stair step.

Truss: Triangular, reinforced rafter.

Underlayment: Thin, smooth plywood or particle board applied over a rough subfloor; covered with carpeting, vinyl tile or other material requiring a smooth base.

Valley: Intersection created by two sloping roofs, generally meeting at right angles.

Vapor Barrier: Thin sheathing to prevent the transmission of moisture through a wall; typically overlapped sheets of polyethylene film.

Ventilation: Air flow through basements, wall cavities, attics, etc. to prevent accumulation of moisture.

Yents: The openings (typically louvered or weatherproof) to allow ventilation.

Voltage: (official) One volt is the voltage between two points of a conducting wire carrying a constant current of 1 ampere, when the power dissipated between these two points is 1 watt. (unofficial) A volt is a measure of the "pressure" of an electrical service.

Wallboard: Commonly, paper-covered gypsum panels.

Warp: Bending along the flat, wide surface of a board or door.

Weep Holes: Small holes drilled in sills or window frames through which condensation escapes; also short sections of pipe placed at the base of retaining walls to release hydrostatic pressure and groundwater.

Zone: Independently controlled section of a heating system (typically hot water).

Nancy Robinson

From: info@criterium-lalancette.com
Sent: Wednesday, June 01, 2016 3:22 PM
To: twnbridg@comcast.net
Subject: 36926 Town of Bridgewater TS09- Radon In Air Test Report
Attachments: 36926 Town of Bridgewater TS09 - 1.9.pdf

Dear Town Select Board & Ms. Robinson,

1.9 pCi/L (picocuries per liter) is the radon-in-air test result. Attached is the report. Please review this information and call with any follow-up questions.

How to interpret your results:

< 4.0 pCi/L (less than 4.0 pCi/L) is below the EPA upper action level of 4.0 pCi/L.

The average indoor radon level is estimated to be 1.3 pCi/L and approximately 0.4 pCi/L is normally found in the outside air. The EPA publication Home Buyer's and Seller's Guide to Radon states, "The EPA believes that any radon exposure carries some risk, no level of radon is safe. Even radon levels below 4.0 pCi/L pose some risk. Radon levels in many homes *can* be reduced to 2.0 pCi/L or less. You can reduce your risk of lung cancer by lowering your radon level."

≥ 4.0 pCi/L (greater than or equal to 4.0 pCi/L) is at or above the EPA upper action level of 4.0 pCi/L.

In the Home Buyer's and Seller's Guide to Radon it states, "The EPA recommends that you take action to reduce your home's indoor radon levels if your radon test result is 4 pCi/L or higher... If elevated levels are found during the real estate transaction, the buyer and seller should discuss the timing and costs of radon reduction."

A list of Vermont and New Hampshire radon mitigators can be found at this link:
http://www.nrpp.info/radon_mitigation_service.shtml

If you would like further information about radon please refer to the following EPA publications:
Home Buyer's and Seller's Guide to Radon : <http://www.epa.gov/radon/pubs/hmbyguid.html>
Consumer's Guide to Radon Reduction: <http://www.epa.gov/radon/pubs/consguid.html>

*This information was last updated 04/2013

Thank you.

Best Regards,

Melissa

Melissa Werle, Environmental Engineering Technician
Criterium-Lalancette Engineers
PO Box 6348
Rutland VT 05702-6348